

1 of 2

Coloma

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID [3463]
	*STATE CODE [55]
	*SHRP SECTION ID [3016]

LOCATION USH 51 2.9 miles South TYPE EQUIP. Stratton Richardson AVC (Traffic COMP III)

MP # of STH 21 MODEL # 241

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
1/5/89		Replace TC3	M. Sisco		T6
1/17/89		"	"		T23
3/20/89		"	"		T2
5/8/89		"	S. Wiswell		T13
8/14/90		"	D. Amherdt		T40
"		Replace SB Piezos (not FPS lane)	"		51 DPOGO 3024 52 DPOGO 3028
9/26/90		replace TC3	D. Amherdt		T45
8/14/90		replace modem	?		#229
7/24/91		replace piezos - all	D. Kitzinger		Thermo- Coax ?

S. Penwell
Piezo Film

North Central Region of FHWA-LTPP
Traffic Data Collection Equipment Installation And Change Log

State Code	SIIRP Id	Location	Install Date	Brand Name	Model	Serial No. Control Unit	GPS Sensor Type	Software Brand/Version	Loops	Equipment Change	Date of Change
55	3015	0.3 MI. S/O CTH D				T51				TC3	09/25/90
55	3015	0.3 MI. S/O CTH D				T79				TC3	11/01/90
55	3015	0.3 MI. S/O CTH D				T68				TC3	11/28/90
55	3015	0.3 MI. S/O CTH D				T45				TC3	03/05/92
55	3015	0.3 MI. S/O CTH D								piezos	07/15/92
55	3016	2.9 MI. S/O ST 21	10/27/88	SR		T10	Piezo cable	Streeter 261/3.6	6x6'12AWG/cond		
55	3016	2.9 MI. S/O ST 21				T6				TC3	01/05/89
55	3016	2.9 MI. S/O ST 21				T23				TC3	01/17/89
55	3016	2.9 MI. S/O ST 21				T2				TC3	03/20/89
55	3016	2.9 MI. S/O ST 21				T13				TC3	05/08/90
55	3016	2.9 MI. S/O ST 21				T40				TC3	08/14/90
55	3016	2.9 MI. S/O ST 21				3024/3028				piezos (SB)	08/14/90
55	3016	2.9 MI. S/O ST 21				T45				TC3	09/26/90
55	3016	2.9 MI. S/O ST 21								modem	08/14/90
55	3016	2.9 MI. S/O ST 21								piezos (all)	07/24/91
55	3016	2.9 MI. S/O ST 21								modem	09/26/91
55	3016	2.9 MI. S/O ST 21				T41				TC3	06/10/92
55	3016	2.9 MI. S/O ST 21				T19				TC3	06/24/92
55	3016	2.9 MI. S/O ST 21				T73				TC3	07/27/92
55	3016	2.9 MI. S/O ST 21				T62				TC3	09/30/92
55	3019	0.85 MI. N/O ST 77	09/11/90	SR		T3	Piezo 8' film	Streeter 261/3.6	6x6'12AWG/cond		
55	3019	0.85 MI. N/O ST 77								piezos	06/20/91
55	3019	0.85 MI. N/O ST 77								modem	08/28/91
55	3019	0.85 MI. N/O ST 77				T41				TC3	09/30/91
55	3019	0.85 MI. N/O ST 77				T132					02/18/92
55	5037	2.1 MI. S/O US 8	09/06/90	SR		T32	Piezo 8' film	Streeter 261/3.6	6x6'12AWG/cond		
55	5037	2.1 MI. S/O US 8				T83				TC3	10/28/90
55	5037	2.1 MI. S/O US 8								piezos	06/17/91
55	5037	2.1 MI. S/O US 8				T106				TC3	07/17/91
55	5037	2.1 MI. S/O US 8				T24				TC3	02/18/92