


TO ALL AUTHORIZED SERVICE ACCOUNTS
AS-1975 MANUAL OWNERS
SUBJECT 1991 L-CAR IGNITION
CHEVROLET BERETTA/CORSICA

No. AS-1128
DATE 11-27-91
FILE IN Bulletin
Binder

THIS IS AN UPDATE TO SERVICE BULLETIN AS-1117


For the 1991 L-Car ignition, the following changes have been made.

NOTE: The 1990 ignition will not fit the 1991 vehicles.




701410 CODED SERVICE LOCK

- ◆ Round Column
- ◆ Non Tilt
- ◆ Manual Transmission
- ◆ Service Key Blank 595311




701409 CODED SERVICE LOCK

- ◆ Round Column (Low Mount)
- ◆ Tilt
- ◆ Manual Transmission
- ◆ Service Key Blank 595313



700580 CODED SERVICE LOCK

- ◆ Round Column (High Mount)
- ◆ Non Tilt
- ◆ Automatic Transmission
- ◆ Service Key Blank 595311



701405 CODED SERVICE LOCK

- ◆ Round Column (Low Mount)
- ◆ Tilt
- ◆ Automatic Transmission
- ◆ Service Key Blank 595313