CLE Engineering, Inc. (508) 748-0937

1494 E. Rodney French Blvd February 2017

Sediment Forebay: 0.1 inch Water Quality Depth : 1 inch

Area	Existing area (sf)	1" Runoff volume from total impervious area (cubic feet)	0.1" Runoff volume from total impervious area (cubic feet)
Existing parking +			
building/deck area	41,700	3,475	348
Net increase in pavement			
(impervious)	0		
Totals:	41,700	3,475	348
		Cross	Volume (cf)
		Sectional Area	(Assume 40%
	Length (ft)	(sf)	void space)
Sediment Forebay			
Available treatment volume	290	4	464
Available treatment volume compared with required volume for			
0.1" over ex. pavement:			134%