

July 31, 2018

**PRODUCT WARNING**  
**COVE DOOR & PANEL SHOWER DOORS**

For the items listed below, we are aware of a few isolated instances where the pin has separated from the pivot hinge which could cause the door to fall off the frame.

All consumers who have purchased any of the doors listed below between January 1, 2018 and July 13, 2018 will be notified by August 3rd by mail, and replacement parts will be mailed to them in mid-September.

For additional information, contact Foremost Customer Service, toll free at 1-888-620-3667 between 8:00 a.m and 6:00 p.m. EST.

List of affected part numbers:

CVDP4269-CL-BN	CVDP5469-CL-BN
CVDP4269-CL-OR	CVDP5469-CL-OR
CVDP4269-CL-SV	CVDP5469-CL-SV
CVDP4269-RN-BN	CVDP5469-RN-BN
CVDP4269-RN-OR	CVDP5469-RN-OR
CVDP4269-RN-SV	CVDP5469-RN-SV
CVDP4869-CL-BN	CVDP6069-CL-BN
CVDP4869-CL-OR	CVDP6069-CL-OR
CVDP4869-CL-SV	CVDP6069-CL-SV
CVDP4869-RN-BN	CVDP6069-RN-BN
CVDP4869-RN-OR	CVDP6069-RN-OR
CVDP4869-RN-SV	CVDP6069-RN-SV