


Differential

Deletion of Secondary Cover

The secondary cover is not used on '95 Legends, so there is no need to remove or install it.



The contents on the following pages in the '94 Legend service manuals are affected by the deletion of the secondary cover.

94 LEGEND S/M (61SP003):

[15-5](#), [15-6](#)