

**Intellinet High-Power Ceiling Mount Wireless 300N PoE Access Point  
- Model 525251 || Hardware Reset -**

How to restore the factory default settings

Firmware Version < 1.16



**Intellinet High-Power Ceiling Mount Wireless 300N PoE Access Point  
- Model 525251 || Hardware Reset -**

Firmware Version >= 1.16

The reset procedure has been changed as of firmware version 2.16. You now have to press the WPS button twice.

1. The first long press triggers the device to reboot, indicated by the flashing LEDs.
2. Then after the restart has been triggered (flashing LEDs), you need to press the WPS button again within 15 seconds.
3. That restores the factory default values.