

JT15D-5A			S/N PCE-100125		
					LH
TSN - 9333.7			TSO - 3527.5		TSHSI: 1737.8
CSN - 8307			CSO - 2954		CSHSI: 1400
Part Name	Part Number	Serial Number	Consumed	Limit	Remaining
Hub Low Compressor	3037911	8T489	8307	12000	3693
Hub Low Compressor Booster	3034112	7T362	8307	14000	5693
Impeller	3033682	8C731	8307	9000	693
Disk High Turbine	3036411	A001TTR6	2954	14000	11046
Disk Low Turbine (Second)	3022212	A001T5HN	2954	14000	11046
Disk Low Turbine (Third)	3036113	2W080	8307	14000	5693
H T Blades	3055021-01	71 Blades	3527.5 TSN		
Accessories					
Fuel Control Unit	3244851-10	B29333 N	3527.5 TSO		
Fuel Pump	717101-1	0088	3527.5 TSO		
Fuel / Oil Cooler	14438-000	1567	3527.5 TSO		
Flow Divider	26395-2	498	3527.5 TSO		
Bleed Valve Actuator	800888-1	F11769	3527.5 TSO		
Bleed Valve Control	800831-1-001	89062431	3527.5 TSO		
Oil Pump Assy	3102616-01	PWV052464JT	3527.5 TSO		
Engine O/H by Pratt& Whitney (WV) on 10/24/2005 @ TSN: 5806.2 CSN: 5353					
Hot Seciton Inspection C/W on 5/2/2012 by Vector Aerospace @ TSN: 7595.9 CSN: 6907					
FINAL TIMES/CYCLES FIGURED BY LOGBOOK REIEW, CESCO REPORT & FLIGHT AWARE					