FALCON 2000

Ser #: 56, Reg#: N365TX May 16, 2025



FLIGHT SOURCE INTERNATIONAL, INC. Sarasota, FL 941-355-9585 | <u>https://flightsource.com/</u>





FALCON 2000 SN #56

| Year Mfr/Dlv: | 1998 / 1998 |
|----------------|--|
| Reg# (Hex): | N365TX (A4209E), Expires: 4/30/30, Previous Reg #N784BX (AA9F91) |
| Purchase Date: | 3/5/20 |
| Location: | AMA/KAMA/Rick Husband Amarillo International Airport, Amarillo, TX - U.S |

| Listed On: | 3/23/2023 Days on Market (785) |
|----------------|---|
| Ownership: | Wholly Owned / Previously Owned |
| Lifecycle/Use: | In Operation / Charter |
| Note: | Owner is looking to sell a 25% share in the aircraft for \$1,375,000. |

| AIRFRAME CURRI VALUE | | IVITY EST. VALUE | S |
|-------------------------|----------|-------------------|--------|
| Data Valid As of | 10/24/24 | 10/24/24 - 5/9/25 | 5/9/25 |
| AFTT (hrs): | 7,798 | 330 | 8,128 |
| Landings/Cycles: | 4,394 | 171 | 4,565 |
| Nautical Miles: | | 122,679 | |

FEATURES

| EQUIPPED WITH | | |
|-------------------------------------|------------------------------------|--|
| Dual IRS | Aft Lavatory | |
| Externally-Serviceable Lav | Flushing Lav | |
| Forward Galley | Engine Maintenance Program | |
| SATCOM | 8.33 channel spacing | |
| High-Speed Data/Wifi | ADS-B Capable | |
| Future Air Navigation System (FANS) | RVSM | |
| STANDARD EQUIPMENT | | |
| Terrain Awareness & Warning System | Auxiliary Power Unit | |
| Thrust Reversers | Single-Point Refueling | |
| Cockpit Voice Recorder | Traffic Collision Avoidance System | |
| Dual Flight Management Systems | Weather Radar | |
| Emergency Locator Transmitter | Flight Data Recorder | |
| NOT EQUIPPED WITH: | | |
| Third Flight Management System | | |



FALCON 2000 SN #56

| n Condition TBO: No | | |
|---|----------|----------|
| aintenance Program: Jet Support Services, Inc JSSI - Prem | ium | |
| MODEL CFE738-1-1B | ENGINE 1 | ENGINE 2 |
| Serial Number | P105252 | P105227 |
| Total Time Since New (TTSNEW) Hrs | 7,798 | 7,798 |
| Time Between Overhaul (TBO/TBCI) Hrs | 5,000 | 5,000 |

| APU: HONEYWELL GT | CP 36-150(F2M) |
|-------------------|-----------------------------------|
| Serial #: | P-162 |
| Maintenance Plan: | Jet Support Services, Inc. (JSSI) |



| AVIONICS | |
|--------------------------|--|
| ADF: | Dual Collins |
| AFIS: | Honeywell |
| Autopilot: | Collins APS-4000 w/dual flight control computers |
| Avionics Package: | Collins Pro Line 4 |
| Communication Radios: | Triple Collins w/8.33 kHz spacing |
| CVR: | Honeywell SSCVR |
| DME: | Dual Collins |
| EFIS: | Collins EFIS-4000 4-tube |
| FDR: | Honeywell SSFDR |
| Flight Rules: | IFR |
| FMS: | Dual Universal UNS-1SE w/SSDTU & control display units |
| GPS: | Dual Collins GPS-4000A |
| Hi Frequency: | Dual Bendix/King w/SELCAL |
| IRS: | Dual Honeywell LASEREF |
| Navigation Radios: | Dual Collins |
| Radar Altimeter: | Collins |
| SATCOM: | AirCell Axxess II Iridium w/multiple headsets |
| TAWS: | Honeywell Mark V EGPWS |
| TCAS: | Collins TCAS-II w/change 7.1 |
| Transponder: | Dual Collins TDR-94D |
| Weather Radar: | Collins |

| ADDITIONAL EQUIPMENT | |
|----------------------|--|
| Cockpit: | ADS-B Out (DO-260B), WAAS/LPV, FANS-1/A, dual flight control computers, dual Collins air data computers, dual audio panels, dual Collins radio tuning units, SBAS, Artex 406 MHz ELT |
| Crew Accessories: | Forward crew rest area |
| Equipment: | Concorde lead acid main battery |

FALCON 2000 SN #56

INTERIOR

| Configuration/PAX: | Executive/12 passengers |
|--------------------|---|
| General: | Fireblocked interior |
| Seating: | Forward 4-place club, dual removable forward-facing seats, aft 4-place conference group opposite 2-place club |
| Refreshment: | Forward full-service galley w/Nespresso De'Longhi espresso maker, warming pot, microwave, warming oven & sink |
| Cabinetry/Wood: | Manual berthing high/low table |
| Entertainment: | Forward 15-inch Airshow bulkhead monitor, CD/DVD player, plug-in monitors |
| Business : | AirCell Gogo Biz w/ATG-4000 broadband internet & Wi-Fi |
| Storage: | Aft in-flight accessible baggage compartment |
| Lavatory: | Externally-serviceable electric-flushing aft lav w/vanity |

EXTERIOR

| Colors: | White w/black metallic |
|----------|-------------------------------------|
| General: | New exterior as reported 03/23/2023 |

MAINTENANCE

| Maintained: | FAR Part 135 | | |
|-------------------------------|--|-----|--------------------------------------|
| Airframe Maint Program: | Unknown | | |
| Airframe Tracking Program: | Unknown | | |
| Certification(s): | B-RNAV, RNP-10, RVSM | | |
| General: | Engines are enrolled on 100% JSSI maintenance program. | | |
| ITEMS | C/W | DUE | NOTES |
| C-Check: | 03/23/23 | | Fresh as reported (Date not actual). |



Flight Source International, Inc.

Sarasota, FL 941-355-9585 | <u>https://flightsource.com/</u>



FALCON 2000 SN #56



