

DODSON INTERNATIONAL

WILLIAMS INTERNATIONAL

MODEL	FJ44-2C
S/N:	1124

R/H

TTE:	3656.8
CYCLES	2720

TSO / Check 4	689.6
CSO / Check 4	478

<i>Inspection</i>	<i>Due</i>	<i>Remaining</i>
Check 1	3836	179.2
Check 2	3822.1	165.3
Check 5	4717.2	1060.4
Check 6	6467.2	2810.4

LIFE LIMITED PARTS LOG

	PART	SERIAL	TOTAL	TOTAL	CYCLE	CYCLES				
DESCRIPTION	NUMBER	NUMBER	HOURS	CYCLES	LIMITER	REMAINING				
FAN ROTOR	61967	AU01278	3656.8	2720	10,000	7,280				
IP COMP ROTOR	61968	AU01329	3656.8	2720	10,000	7,280				
HP COMP ROTOR	61964	HW18874	2262.2	1752	8,000	6,248				
HP TURB DISK	59387	RRL7LD12001	3656.8	2720	8,000	5,280				
1ST LP TURB DISK	55531	RRL7S01663	3656.8	2720	10,000	7,280				
2ND LP TURB DISK	55534	RRL7S01528	3656.8	2720	10,000	7,280				

All Times/Cycles from Engine Logs & AF Log Entries- Log Review Completed

NOTE 1: HP Comp Rotor Replaced NEW by Williams International 06-13-2005 @ TSN: 1394.6 CSN: 968

NOTE 2: Checks 1, 2 & 4 C/W 11-15-2011 @ TSN: 2967.2 CSN: 2242

NOTE 3: Check 2 C/W on 8/14/2012 @ TSN: 3222.1 CSN: 2411

NOTE 4: Check 1 C/W on 12-31-2013 @ TSN: 3536 & CSN: 2624