

Release Notes
January 21, 2018

BrightSign®

BRIGHTAUTHOR RELEASE NOTES

Version 4.7.2.8

BrightSign, LLC. 983-A University Ave., Los Gatos, CA 95032 | 408-852-9263 | www.brightsign.biz

BrightAuthor Requirements

- PC with Windows Vista, Windows 7, Windows 8, or Windows 10—plus Microsoft .Net Framework 4.6 or later
- XTx44, XTx43: **Minimum Required Firmware: 7.1.49**
- HDx24, LS424: **Minimum Required OS: 8.0.6.6**
- XDx34, XDx33, HDx23, LS423, HO523, HS123: **Minimum Required Firmware: 6.2.39**
- 4Kx42, XDx32, XDx30, HDx22, HDx20, LSx22, AU320: **Minimum Required Firmware: 5.1.33**

Changes Since 4.7.2.5

New Features

- Localization support for the following languages: Chinese, French, German, Italian, Japanese, Portuguese, Russian, Spanish, Turkish

Improvements

- The language selection for a localized BrightAuthor install now applies to all Windows users (not just the user who performed the install).