



# FIRMWARE RELEASE NOTES

Version 6.2.147.2 (BrightSign XTx43, XDx33, HDx23, LS423)

## Changes Since 6.2.147

### Improvements

- The WPA2 implementation has been patched to account for KRACK vulnerabilities.