

Manufacturer $BE//A$ Serial $29/-7$ Date of Manufacture	WCA M	egistration Number	745 LS
Engine(s) currently installed:			
Manufacturer TEXTRON A	LYCOMNO Model 0-32	0-A2D Ser	ial L-48902-27A
Manufacturer		Ser	ial
Propeller(s) currently installe	d:		
Manufacturer SENSEN (odel 74DM65	8-1-56
HUB Model	Serial	Ser	and the same of th
Blade Model	Serial	Serial	Serial
Blade Model	Serial	Serial	Serial

YEAR 20 /O DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entres)
5/11/200	3068.95			OPENED OF AIRCHAFT FOR A looke Ingression
11.4				holed Allpivot Foin 15, Relleys. Replace Pur
				Brake pad linings wiTH NEW. CHENNED June
				WHE BEALISS And REPARKED MAINS AND TOIL
				REMOVED BATTERY TVAY CHEMED, INSPECTED
				And painted, Secreted AFT STringER. EIT
				bATTERY IS ON ORDER. AD NOTES complied
				w.174.
				ADTA-18-03 CALLE CORROSION Insp of w de EA look
-				AD 72-20- OF AGROBATIC PLACAND.
				AD75-17-76 Power 655 c/w die EA polit
				AO 89-18-06 FUT Folding SEATS C/L AS PERSINA
				AD 2000 - 25-02 R1 EFF 07-13-01 Front And
				REAR SPARE O'LE EA 12 months. Clemed
				Fill sump And RESATTIED, KAR CHECK "OK"
h	20			lubed TACH CABLE. I CENTIFY THIS ALLAST
Also I	111			HAS been I. A.W. And looke Inspection
STAN STAN	red A	103/5/	954	And Found To be Airmostly ASOFTH'S DATE. Spipat

YEAR 20/O DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5/12/2010	3068.95		3048.95	Annual inspection completed this date per the
				FAR 43 Appendix D checkerst. Checked ELT por
				FAR 91.207 (d) new buttery installed ph BP-1010.
				Battery due 7-2012, AD's checked three 2010-09
				Issue Aventest CD-ROW. No AD's due this date
				Aircraft approved for return to service this
				date, Burrows Aumtren Lee by it's member:
				mott & Burns
2000				41831456741A
5/13/2010	3068.95		3068.95	INSTALL NEW SENED CONCORDE BATTON
				RO-35A 40354920
5-28-2011	3105.8		3108.8	INSTALLED NEW 8:50 x 6 TIRES AND
	100			tubes per STC SAYYRAC SEE
				COPY OF STC and 337 IN AIRCRAFT
				RECOMPT.
				Culch Pent 2169 140 ATP

YEAR 20 / (DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
			Date: 5/. Total Tin Inspecte 91.207 (note on i AD09-22 Remover certify the	Citabria 7GCAA SN: 291-74 N745LS 27/2011 ne: 3105.87 Tach Time: 3105.87 d airframe in accordance with FAR part 43 Appendix D. Tested ELT per FAR d) and found it inoperative. Removed Narco ELT10 SN6748 and installed instrument panel. Complied with AD72-18-03, AD75-15-16m AD00-25-02R1 -02by inspection per body of AD. No other recurring AD applicable. d ACK encoder A-30 SN:92211 and installed ACK encoder A-30 SN:122887. I least this aircraft has been inspected per FAR part 43 Appendix (d) and found an airworthy condition. Aircraft returned to service this date.
3 Septal	3123.0	L 31	cony 1	899856 INST ELT a Tested
4/1/2012	3145.56		3142.20	Profession femano, cuarinalists and reflicated, man 1 reinstances Acopenius and tenences prof. S/N: 44948. Air 2754837 14

5.)

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	with butyrate d removed, inspe Cowling and all fabricated and i 219-8-1. Replac brake lines. Ser	5.56 Tach 1 rudder and ope. Minor fi cted and reir fairings rem nstalled. Fu- ed brake ma viced brakes ed with new aft rerigged	elevators remo abric repairs m stalled. Tail w oved, sanded a el selector repl ster cylinders v with 5606. Rep MIL 6000 hos IAW Bellanca S	ove. All fabric sanded and refinished nade as required. Wheels and brakes ires removed, cleaned and reinstalled, and repainted. New floor and interior blaced with American Champion P/N 2- with Cleveland P/N 10-54. Replaced spaired elevator trim cables. All rubber se. Reassembled aircraft with all new Service Manual.
	manual, table 3- 6/2014. Compl inspection per b	me in accord 1. Tested El ied with AD7 ody of AD. I bearings. Lu ted per FAR aft returned	ime: 3145.56 lance with FAR LT per FAR 91 72-18-03, AD79 No other recur ubricated all pi part 43 Appen to service this	R part 43 Appendix D and Bellanca Service 207 (d) and found operative, batteries due 5-15-16m AD00-25-02R1, AD09-22-02by rring AD applicable. Inspected brakes, ulleys and hinges. I certify that this aircraft ndix (d) and found to be in an airworthy

YEAR 2012 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME II SERVICE	N En Tec	escription of Inspections, Tests, Repairs and Alteration stries must be endorsed with Name, Rating and Certificate Number of chnician or Repair Facility. (See back pages for other specific entries)
18 Sep	3177.22			Re	gland Fail wheel /www attala 700000
			Date: 5/8, Total Time Performed D and Bell operative, 25-02R1. A applicable inspected alrworthy	/2013 e: 3187.05 d ANNUAL in anca Service batteries du AD09-22-02b . Lubricated per FAR part condition. A	Tach Time: 3187.05 spection on airframe in accordance with FAR part 43 Appendix manual, table 3-1. Tested ELT per FAR 91.207 (d) and found see 9/2014. Complied with AD72-18-03, AD75-15-16m AD00-winspection per body of AD. No other recurring AD all pulleys and hinges. I certify that this aircraft has been 43 Appendix (d), ANNUAL INSPECTION and found to be in an aircraft returned to service this date.
4406	3213,0	5		ch	wood ent oil 80ts Phill 100+
	YEAR REC	***	TODAY'S	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entries)

YEAR 20 DATE	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and A Entries must be endorsed with Name, Rating and Certificate Technician or Repair Facility. (See back pages for other spec
	and found ope 16m AD00-25- AD applicable, inspected per an airworthy o Ryan A. Pernbe Bellanca Citabria Date: 9/25/2015 Total Time: 3221 Performed ANNU	In 13.08 Tach INUAL inspection	time: 3213.0 tion on airfrarervice manual rivies due 9/20. 22-02by inspeall pulleys and Appendix (d), rcraft returner 54837 IA 11-74 N745L5	me in accordance with FAR part 43 , table 3-1. Tested ELT per FAR 91.207 (d) 14. Complied with AD72-18-03, AD75-15- action per body of AD. No other recurring lininges. I certify that this aircraft has been ANNUAL INSPECTION and found to be in d to service this date.
	Bellanca Service r found operative, inspection per bo hinges. I certify th	manual, table ; betteries due dy of AD. No lat this aircrafi ound to be in	3-1. Replaced El 12/2020. Comp other recurring t has been inspe an airworthy co	LT batteries and tested per FAR 91.207 (d) and plied with ADOO-35-0281, ADOO-22-02 by AD applicable. Lubricated all pulleys and steed per FAR part 43 Appendix (d), ANNUAL undix (G). Aircraft returned to service this date.

YEAR							15	, Tests	s. Repair	s and Alte
20										
DATE	Bellanca Date: 9/2		A SN: 291-74	N745LS			36	back p	ages for or	ther specific
	Total Tim	3233.97 hrs		3233.97 hrs						
	Performer Fellows 5	ANNUAL ins	pection on air	rframe in acco	ordance with FAR	art 43 Appendix D	and			
-	batteries o	ue 12/2020.	Complied wi	th ADOD-25-03	FAR 91.207 (d) a	d found operative	4			
	be in an air	worthy condi	tion. Aircraft	returned to s	ervice this date.	SPECTION and for	and to			
	Ryan A. P.	mberton A&	P 2754837	10 0	0_					
				-17	,,,,,					
-	Bellanca Cita	oria 7GCAA SI	N: 291.74 N7.	ASIC						
	Date: 10/27/	2017								
	Total Time: 3									
	Bellanca Servi	pe manual, ta	tion on airfra ble 3-1. Test	me in accorda	ance with FAR pa IR 91.207 (d) and	t 43 Appendix D a	nd			
	AD. No other	12/2020. Co	mplied with	AD00-25-02R1	1, AD09-22-02 by	ound operative, respection per bod	lv of			
	Lubricated all	bulleys and hi	Immer County	Special Bill	repacked main w	heel bearings.				
	Appendix (d), returned to se	WNUAL INSP	ECTION and	found to be in	craft has been ins an airworthy co	dition. Aircraft	rt 43	-		
				00)	-2010/00/00/00/00/00/00/00/00/00/00/00/00/				
	Ryan A. Per	nberton A&P	2754837 W	Kh	ma					
_	-			.,						
			1	-						
							-			
				-						
VEAD	BE.							Tost	e Renair	re and Al
YEAR 20	RF" Ti				1			Test	ts, Repair	rs and Alt
YEAR 20 DATE	Ti Ti	ellatica Citah	ria 7GCAA St	N: 291-74 N74	1515), R	ts, Repair ating and C pages for C	Certificate N
20	Ti B	rte: 1/7/2019	9), R	ating and C	Certificate N
20	Ti B	ite: 1/7/2019 tal Time: 32!	9 58.17 hrs. T	ach Time: 325	58.17 hrs		annothing to un	ick	ating and C	Certificate N
20	Ti B	te: 1/7/2019 tal Time: 32! rformed ANI flanca Service	9 58.17 brs. T NUAL Inspect te manual, ta	ach Time: 325 tion on airfran ble 3-1. Tests	58.17 hrs me in accordance od ELT per FAR 9:	with FAR part 43 A 207 (d) and found	operative,	a, R	ating and C	Certificate N
20	T. TI 8	te: 1/7/2019 tal Time: 32! rformed ANI flanca Servic tteries due 3	9 S8.17 hrs. T NUAL Inspect te manual, ta 12/2020. Co	ach Time: 325 tion on airfrar ble 3-1. Tests raplied with A	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-02R1, Al	207 (d) and found 09-22-02 by Inspe	operative, ction per bod	s, R	ating and C	Certificate N
20	Ti B D. To Pe Be be an Ai	te: 1/7/2019 tal Time: 32! rformed ANI flanca Servic tteries due 1). No other r craft has be-	9 58.17 hrs. T NUAL inspec- ce manual, ta 12/2020. Co recorring AD en inspected	ach Time: 325 tion on airfran ble 3-1. Tests raplied with A applicable. U per FAR part	58.17 hrs me in accordance od ELT per FAR 9: ADD00-25-02R1, Al arbricated all pulli 43 Appendix (d),	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B D. To Pe Be be an Ai	te: 1/7/2019 tal Time: 32! rformed ANI flanca Servic tteries due 1). No other r craft has be-	9 58.17 hrs. T NUAL inspec- ce manual, ta 12/2020. Co recorring AD en inspected	ach Time: 325 tion on airfran ble 3-1. Tests raplied with A applicable. U per FAR part	58.17 hrs me in accordance od ELT per FAR 9: ADOD-25-0281, Al arbricated all pull	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B B D Tr	rte: 1/7/2015 tal Time: 32: rformed ANI flanca Servic tteries due 2). No other r craft has bei in an airwor	9 58.17 hrs. T. NUAL inspec- te manual, ta 12/2020. Cor recurring AD en inspected rthy conditio	ach Time: 325 tion on airfrar ble 3-1. Tests raplied with A applicable. U per FAR part n. Aircraft ret	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-0281, Al ubricated all pull 43 Appendix (d), turned to service	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B B D Tr	rte: 1/7/2015 tal Time: 32: rformed ANI flanca Servic tteries due 2). No other r craft has bei in an airwor	9 58.17 hrs. T. NUAL inspec- te manual, ta 12/2020. Cor recurring AD en inspected rthy conditio	ach Time: 325 tion on airfran ble 3-1. Tests raplied with A applicable. U per FAR part	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-0281, Al ubricated all pull 43 Appendix (d), turned to service	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B B D Tr	rte: 1/7/2015 tal Time: 32: rformed ANI flanca Servic tteries due 2). No other r craft has bei in an airwor	9 58.17 hrs. T. NUAL inspec- te manual, ta 12/2020. Cor recurring AD en inspected rthy conditio	ach Time: 325 tion on airfrar ble 3-1. Tests raplied with A applicable. U per FAR part n. Aircraft ret	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-0281, Al ubricated all pull 43 Appendix (d), turned to service	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B B D Tr	rte: 1/7/2015 tal Time: 32: rformed ANI flanca Servic tteries due 2). No other r craft has bei in an airwor	9 58.17 hrs. T. NUAL inspec- te manual, ta 12/2020. Cor recurring AD en inspected rthy conditio	ach Time: 325 tion on airfrar ble 3-1. Tests raplied with A applicable. U per FAR part n. Aircraft ret	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-0281, Al ubricated all pull 43 Appendix (d), turned to service	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti Ti B D Ti Pi Bi bi bi Ai ai be	ite: 1/7/2019 tal Time: 32! rformed ANI flants Servic tteries due 1 0. No other r craft has be- in an airwor Ryan A. Per	9 58.17 hrs. T MUAL inspecte manual, ta 12/2020. Ca recorring AD en inspected rithy conditio mberton A& ria 7GCAA SA	ach Time: 325 tion on airfrar ble 3-1. Tests raplied with A applicable. U per FAR part n. Aircraft ret	58.17 hrs me in accordance od ELT per FAR 92 AD00-25-0281, Al abricated all pull 43 Appendix (d), turned to service A R R R R R R R R R R R R	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti B D Tr	rter 1/7/2019 tal Time: 32! rformed ANI flanca Servic tteries due 1 0. No other r craft has be- in an airwor Ryan A. Per flanca Citabr te: 3/13/202	PAGE TO SELECTION OF THE SELECTION OF TH	ach Time: 325 tion on airfrar ble 3-1. Tests made with A applicable. U per FAR part n. Aircraft ret P 2754837 U	S8.17 hrs me in accordance od ELT per FAR 9: Ab00-25-0281, Al aboricated all pull 43 Appendix (d), turned to service A A A A A A A A A A A A A	.207 (d) and found 09-22-02 by Inspe ys and hinges. I ce ANNUAL INSPECTION	operative, ction per bod rtify that this	y of	ating and C	Certificate N
20	Ti Ti B D Tr Pe Bi bi Ai ai bi C D Tr Tr Pe Bi C D Tr	te: 1/7/2019 tal Time: 32! rformed ANI flanta Servic tteries due 3 No other r craft has be- in an airwor kyan A. Pen flanca Citabr te: 3/13/202 al Time: 327 formed ANI	S8.17 hrs. T NUAL inspecte remanual, is 12/2020. Corecurring AD en inspected rithy condition miberton A& ris 7GCAA SN 10 17.78 hrs. Tr	ach Time: 325 tion on airfran ble 3 L. Tests mplied with A applicable. U- per FAR part n. Aircraft ret P 2754637 U t: 291-74 N74 ach Time: 327	58.17 hrs me in accordance od ELT per FAR 9: AD00-25-02R1, Ai ubricated all pull 43 Appendix (d), turned to service A Appendix 55LS 77.78 hrs me in accordance	207 (d) and found 09-22-02 by inspe 92-202 by inspe 93-202 by inspe exampled lines I ce ANNUAL INSPECTI this date.	operative, ction per bod- rtify that this DN and found	t, Rick	ating and C	Certificate N
20	Ti Ti B D Ti Be Be Be Da To Pe Re	te: 1/7/2019 tal Time: 32! rformed ANI flanca Servic tteries due 1). No other r craft has bei in an airwor tyan A. Per llianca Citabr te: 3/13/202 fformed ANI llanca Servici	SS 17 hos T NUAL inspecte remanual, ta 12/2020. Co recorring AD en inspected rithy condition mberton A& 10/200. The second of the 10/200. The second of the 10/200. The second of the 10/200. The second of the second of the 10/200. The second of the second	ach Time: 325 tion on airfran ble 3-1. Tests mplied with A applicable. U per FAR part n. Aircraft rei P 2754637 U s: 291-74 N74 ach Time: 327 tion on airfran ble 3-1. Repli	58.17 hrs me in accordance od ELT per FAR 92 Ab00-25-0281, Al ubricated all pull 43 Appendix (d), turned to service A Ry Rus 4515 77.78 hrs me in accordance aced ELT batteria	207 (d) and found 09-22-02 by inspe ys and linges. I ce ANNUAL INSPECTI this date. with FAR part 43.4 s and tested ELT p	operative, ction per bod- rtify that this DN and found Appendix D ai	t, Rick	ating and C	Certificate N
20	Ti Ti B D Ti Be Be Da To Pe Be	ter 1/7/2019 tal Time: 321 rformed ANI flanca Servic tteries due 1 0. No other r craft has bei in an airwor Ryan A. Per llianca Citabre: 3/13/202 tal Time: 327 formed ANI flanca Servic 1 found oper	PRIVAL Inspecte manual, to 12/2020. Co recorring AD en inspected rithy condition miberton A& 10/27, 78 hrs. To VUAL inspected rative, batter, batter, active,	ach Time: 325 tion on airfrar ble 3-1. Tests mapplicable. U- per FAR part n. Aircraft ret P 2754837 U I: 291-74 N74 ach Time: 327 tion on airfrar ble 3-1. Repli	58.17 hrs me in accordance od ELT per FAR 92 AD00-25-0281, Al abricated all pull 43 Appendix (d), turned to service A Ry Rus 77.78 hrs me in accordance aced ELT batteria 24. Complied w	207 (d) and found 09-22-02 by inspe ys and finges. In ANNUAL INSPECTIVE this date. with FAR part 43 s and tested ELT p th AD00-25-02R1,	operative, ction per bod- rtify that this ON and found Appendix D ai er FAR 91.20 AD09-22-02 b	t, Rick	ating and C	Certificate N
20	Ti Ti S D Tr Pr Si bis Ai ai be Ca To Pe Be an ins	rformed ANI flanca Service terries due 3 No other r craft has be- in an airwor tyan A. Pan flanca Citabr te: 3/13/202 al Time: 327 formed ANI lanca Service f found oper pees 1 certify	PAGE 17 PCL TO SERVICE	ach Time: 325 tion on airfrar ble 3-1. Tests mplied with A applicable. Is per FAR part n. Aircraft ret P 2754637 Is is: 291-74 N74 ach Time: 327 tion on airfrar ble 3-1. Replies due 9/20. No other rec craft has beer	S8.17 hrs me in accordance od ELT per FAR 9: Aboto-25-0281, abbricated all pull 43 Appendix (d), turned to service A Recordance as in accordance aced ELT batteria 24. Compiled uninspected per i	207 (d) and found 09-22-02 by inspec ye and hinges. I ce eanNUAL INSPECTA this date. with FAR part 43 /s a and tested ELT p , ble. Lubricated all AR part 43 Appen	Appendix D are FAR 91.20: AD09-22-02 to pulleys and dix (d), ANNU	to d	ating and C	Certificate N
20	Ti Ti S D Tr Pr Si bis Ai ai be Ca To Pe Be an ins	rformed ANI flanca Service terries due 3 No other r craft has be- in an airwor tyan A. Pan flanca Citabr te: 3/13/202 al Time: 327 formed ANI lanca Service f found oper pees 1 certify	PAGE 17 PCL TO SERVICE	ach Time: 325 tion on airfrar ble 3-1. Tests mplied with A applicable. Is per FAR part n. Aircraft ret P 2754637 Is is: 291-74 N74 ach Time: 327 tion on airfrar ble 3-1. Replies due 9/20. No other rec craft has beer	S8.17 hrs me in accordance od ELT per FAR 9: Aboto-25-0281, abbricated all pull 43 Appendix (d), turned to service A Recordance as in accordance aced ELT batteria 24. Compiled uninspected per i	207 (d) and found 09-22-02 by inspe ys and finges. In ANNUAL INSPECTIVE this date. with FAR part 43 s and tested ELT p th AD00-25-02R1,	Appendix D are FAR 91.20: AD09-22-02 to pulleys and dix (d), ANNU	to d	ating and C	Certificate N
20	Ti Ti S D Tr Pr Si	ter 1/7/2019 tal Time: 32! rformed ANI flanca Service tteries due 3 No other r craft has ber in an airwor kyan A. Pen flanca Citabr te: 3/13/202 al Time: 327 formed ANI flanca Service found oper pection per l ges. I certify pPECTION an	PISS 17 how T NUAL inspects to manual, to 12/2020. Corecurring AD en inspected fifthy conditio miberton A& ria 7GCAA SN 10 17.78 hrs Ti NUAL inspect e manual, to rative, batter body of AD. that this air d found to b	ach Time: 325 tion on airfran ble 3 1. Tests mplied with A applicable. Us per FAR part n. Aircraft ret P 2754637 Us se: 291-74 N74 ach Time: 327 tion on airfran ble 3-1. Replantes due 9/20; No other rec craft has bees le in an airwo	SS.17 hrs me in accordance od ELT per FAR 9: ADD00-25-02R1, Al addricated all pulli 43 Appendix (d), turned to service AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	207 (d) and found 09-22-02 by inspec ye and hinges. I ce eanNUAL INSPECTA this date. with FAR part 43 /s a and tested ELT p , ble. Lubricated all AR part 43 Appen	Appendix D are FAR 91.20: AD09-22-02 to pulleys and dix (d), ANNU	to d	ating and C	Certificate N
20	Ti Ti S D Tr Pr Si	ter 1/7/2019 tal Time: 32! rformed ANI flanca Service tteries due 3 No other r craft has ber in an airwor kyan A. Pen flanca Citabr te: 3/13/202 al Time: 327 formed ANI flanca Service found oper pection per l ges. I certify pPECTION an	PISS 17 how T NUAL inspects to manual, to 12/2020. Corecurring AD en inspected fifthy conditio miberton A& ria 7GCAA SN 10 17.78 hrs Ti NUAL inspect e manual, to rative, batter body of AD. that this air d found to b	ach Time: 325 tion on airfrar ble 3-1. Tests mplied with A applicable. Is per FAR part n. Aircraft ret P 2754637 Is is: 291-74 N74 ach Time: 327 tion on airfrar ble 3-1. Replies due 9/20. No other rec craft has beer	SS.17 hrs me in accordance od ELT per FAR 9: ADD00-25-02R1, Al addricated all pulli 43 Appendix (d), turned to service AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	207 (d) and found 09-22-02 by inspec ye and hinges. I ce eanNUAL INSPECTA this date. with FAR part 43 /s a and tested ELT p , ble. Lubricated all AR part 43 Appen	Appendix D are FAR 91.20: AD09-22-02 to pulleys and dix (d), ANNU	to d	ating and C	Certificate N

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) 20
R I. W AD IZ NA	16 12 + 16 12 + 16 12 + 16 12 + 17 12 12 12 12 12 12 12 12 12 12 12 12 12	PO AN CAO NO TWSP REAR NO CERT	1+4) 024 R PAI 0 BAC LES C/ 75-17-1 R AGAIN ECTION 15AGE 15468 C 15468 C	LUBBO CONTROLS OK ELT JAW AR 91.207 (4) OK BATTERTS DUE REMOVED INSTRUMENT PANEL WITH REINSTALLED. CK BRAKES WHIERE BEARINGS. AD 72-18-03 RUDDER WAT INSPRCTION, NO FURTHER OCTION GONRS ALTERNATE AIR VALUE C/W AS 12 MONTHS. AD 89-18.06 SEATRACH CRACKS DUE AGAIN 12 MONTHS. AD 00-25-02R1 WIST INSPRCTION, DUE AGAIN IN 12 MONTS CAME. C/W BY INSPRCTION OUE AGAIN IN 12 MONTS GOS DUE BY THIS TIME. SEE AD LIST THIS INSPECTION AND FOUND AIR WORTHS. INSPECTION AND FOUND AIRWORTHS.

ORDING H	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			N745LS TACH:3363.2 Performed annual inspection IAW Bellanca Service Manual and FAR part 43 appx. D. Checked ELT, battery due 09/2024. All ADs complied with at this time. See AD list supplied to customer. This aircraft is approved for return to service and is in an airworthy condition. WHATH WILLIAM WILLIAM WILLIAM WILLIAM WILLIAM WILLIAM WILLIAM A&P 3271088 IA