Service Receipt from

Park Place Lexus Plano

2024 LEXU TX350 - STK# PLDP243805 - Mileage 47 5TDAAAB65RS001096

TOTAL REPAIRS INVOICE # ADVISOR \$5,977.43 1089096 102731

SUMMARY

A:DS - DENT SERVICES INV#

DENT SERVICES INV# 15625

B:HAIL - HAIL REPAIR

PLEASE CHECK MOLDINGS

C:24LC03R1 - 24LC03 - UPDATE ENGINE CONTROL ECU SOFTWARE

SPECIAL SERVICE CAMPAIGN 24LC03 - Multiple Models - MIL ON w/DTC P05CE00 Software Update.

D:HAIL - HAIL REPAIR

PLEASE REPAIR AND RE FINNNISH DRIVER DOOR B PILAR AND DOOR FRAME INSIDE PART BY B PILAR AND SEAL DAMAGED IN AUCTION

E:24LA05R1 - 24LA05 - REPLACE CURTAIN SHIELD AIR BAG

SAFETY (NONCOMPLIANCE) RECALL 24LA05 (Remedy Notice) - Certain 2024 Model Year TX350 TX500H TX550H+ - Curtain Shield Airbags May Not Deploy As Intended.

F:HAIL - HAIL REPAIR

PLEASE REPLACE DRIVER SIDE SEAL DAMAGED IN AUCTION AND ADVISE TNX

G:HAIL - HAIL REPAIR

PLEASE REPLACE FONT DOOR DRIVER SIDE WEATHER STIPE DAMAHGED

Invoice Total \$5,977.43

Park Place Lexus Plano 6785 Dallas Pkwy Plano, TX 75024 8665676012