


Processing Delays OTX5844 ORX5804



Please note:

- All processing and audio - video - delays are measured in total of both modules OTX5844 and ORX5804.
- AV measurement inaccuracy varies between -2 ms and 2 ms.

TG700 > OTX5844 > ORX5804 > WFM8300

SDI Input	Delay-V	Delay-H	AV-Delay[ms]
625i 50	0 line	0.074 us delayed	1
525i 59.94	0 line	0 us delayed	1
1080i 50	0 line	0.013 us delayed	1
720p 50	0 line	0.027 us delayed	1
1080p 25	0 line	0.027 us delayed	0
720p 25	0 line	0.027 us delayed	0
1080i 59.94	0 line	0 us delayed	1
720p 59.94	0 line	0.013 us delayed	2
1080p 29.97	0 line	0.013 us delayed	1
1080i 60	0 line	0 us delayed	1
720p 60	0 line	0.027 us delayed	2
1080p 30	0 line	0.013 us delayed	1
720p 30	0 line	0.013 us delayed	1
1080p 24	0 line	0.013 us delayed	0
1080p 23.97	0 line	0.013 us delayed	0
1080psF 23.97	0 line	0 us delayed	1
1080psF 24	0 line	0.013 us delayed	1
1080p 50	0 line	0.013 us delayed	1
1080p 60	0 line	0.027 us delayed	1
1080p 59.94	0 line	0.040 us delayed	1