

CARE AND MAINTENANCE

Spot clean using a mild water-free solvent. Only a professional cleaner should undertake a complete overall cleaning.

The use of steam or water-based cleaners may cause excessive shrinking or staining.





NOTICE

* Please make sure that you have all parts indicated before you begin assembly of this item

* This item should be assembled on a soft surface to prevent scratching the finish during assembly

* This item may require periodic tightening.


PART LIST AND HARDWARE LIST

PIECE	DESCRIPTION	PICTURE	QUANTITY
A	BACK CHAIR		1X
B	SEAT FRAME		1X
C	FRONT LEGS (R & L)		2X
HW1	LONG BOLT	6.3*1.3*75 mm 	4X
HW2	SHORT BOLT	6.3*1.3*40 mm 	2X
HW3	NUT	7.8 mm 	4X
HW4	SPRING WASHER	8.5 mm 	10X
HW5	WASHER	8.5 mm 	10X
HW6	ALLEN KEY	4 mm 	1X
HW7	WRENCH	13 mm 	1X

SAFAVIEH FURNITURE

Model #: DCH9217-SET 2

Product Dimensions: 18-1/2"W x 21"D x 38"H





Weight capacity: 275lbs

WARNING: DO NOT STAND ON CHAIR

WARNING: DO NOT OVER TORQUE BOLTS

PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.
If any part is missing or damaged, do not attempt to assemble the product.
Estimated Assembly Time: 10 minutes.
Tools Required for Assembly (included): Allen Key

 Diagram illustrating the assembly of the base frame. The main frame consists of a curved base (A) and a vertical support (B). Two side panels (X2) are being attached. Callout 'a' shows the bottom of the frame with screws HW1, HW2, HW3, HW4, HW5, and HW6. Callout 'a'' shows a side panel (X2) being secured with screws HW1, HW2, HW3, HW4, HW5, and HW6. Callout 'b' shows the bottom of the frame with screws HW1, HW2, HW3, HW4, HW5, and HW6. Callout 'b'' shows a side panel (X2) being secured with screws HW1, HW2, HW3, HW4, HW5, and HW6.	 Diagram illustrating the assembly of the top frame. The main frame consists of a curved base (A) and a vertical support (B). A top bar (C) is being attached to the top of the frame. Callout 'c' shows the top bar (C) being attached to the top of the frame. Callout 'c'' shows the top bar (C) being attached to the top of the frame with screws HW4, HW5, HW6, and HW7.
STEP 1	STEP 2