

March 29, 1966

ENGINEERING MEMO #142

TO: Memo Distribution
FROM: R. G. Fuller
SUBJECT: REAR SPRING SHACKLE ASSEMBLY INSTRUCTIONS

Because of the frame bracket being welded to the frame at the rear spring shackle instead of bolted as it was previously, it has become quite important that the left spring shackle be assembled with the loose plate on the inside to make service possible, without involving the fuel tank.