

January 31, 1969

ENGINEERING MEMO #251

TO: Memo Distribution

FROM: B. Lewis

SUBJECT: REVISIONS & IMPROVEMENTS-"ISRAEL DIESEL CONVERSION"

Effective at once on all "Israel Diesel Conversion" cars not yet shipped from the factory, the following revisions must be incorporated.

- A. Use plastic Washer #626812 under taillamp door screws.
- B. Reroute speedometer cable through unused clutch rod hole in floor pan to avoid kinking.
- C. Use modified Rear Door Hinge #645919-& 20 to limit rear door swing.
- D. Reroute and clip instrument panel and underhood wiring for better appearance and service accessibility.
- E. Following is a complete list of Parts to be affected:

ITEM	NAME	B OF M	OLD PART NUMBER	NEW PART NUMBER	I	A	REMARKS
.	Plate A.-Power Strg.Pump Mtg. (Diesel)	M	703073	Chgs."A" & "B"	YES	NO	Use W/O Obsoles. except Israel
2.	Bracket-Power Strg.Mtg. Plate-Front (Diesel)	M	704171	Chg:"C"	YES	NO	Use W/O Obsoles. except Israel
3.	Bracket-Power Strg.Mtg. Plate-Rear (Diesel)	M	704172	Chg:"A"	YES	NO	Use W/O Obsoles. except Israel
4.	Brace-P.S.Pump Adj. (Diesel)	M	704205	704622	YES	NO	Use W/O Obsoles. except Israel
5.	Brace-Alternator Mtg.	B	702559	-----	NO	NO	Use W/O Obsoles. except Israel
6.	Brace-Alt.Adj.W/O A.C(Diesel)	M	704399	704623	YES	NO	Use W/O Obsoles. except Israel
7.	Bracket-P.S.Pump Adj. Brace (Diesel)	M	704174	704624	YES	NO	Use W/O Obsoles. except Israel
8.	Hinge A.,Rr.Door Lwr.Spec.	M	.631393 631394	645919LH 645920RH	NO	YES	Revise Usage
9.	Washer-#8 x 5/16 O.D.Plastic	B	626812	-----	NO	YES	Increase Usage