

October 8, 1970
 "A"Rev. 10-12-70
 "B"Rev. 11-24-70
 Chassis # Added 4-7-71

ENGINEERING MEMO #287

TO: Engineering Memo Distribution
 FROM: C. Bland
 SUBJECT: REAR WINDOW DEFOGGER REVISION

The vendor that supplies the rear window defogger unit has requested Checker Motors to adapt to the new standardized rear window defogger.

This change will be made without obsolescence of 645664-Blower Asm. on hand and committed for.

649356-Field Installation, Rear Window Defogger drawing will show rework of 634025-Panel, Shelf with change "F" to service present rear window defogger installation.

The following is a complete list of parts affected.

ITEM	NAME	B OF M	OLD PART NUMBER	NEW PART NUMBER	I	A	REMARKS
1.	Panel-Shelf	M	634025	Chg:"F"	YES	NO	Rework as Required
2.	Blower A.-Rr.Wdo.Defog.	B	645664	647510	NO	NO	Use W/O Obsoles.
3.	Grille A.-Air Outlet	B	645665	647509	NO	NO	Serv.or Sc.Surplus
4.	Cover-Hole Trim	B	644488	646281	NO	NO	Serv.or Sc.Surplus
A 5.	Panel-Aux.Shelf Special	M	638041	Chg:"K" Chg:"L"	YES	NO	Rework as Required
6.	Pnl.-Shelf Tr.-Rr.Wdo.Defog.	M	644490	Chg:"C"	NO	NO	Serv.or Sc.Surplus
7.	Pnl.-Shelf Tr.-Rear Window Defogger-Spec.	M	644491	Chg:"D"	NO	NO	Serv.or Sc.Surplus
8.	Lockwasher-#10 Ext.Tooth	B	138479	-----	NO	YES	Reduce Usage
9.	Nut - #10-24 Hex.	B	120361	-----	NO	YES	Reduce Usage
10.	Lockwasher-#8 Ext.Tooth	B	-----	121752	NO	YES	Increase Usage
11.	Nut - #8-32 Hex.	B	-----	120622	NO	YES	Increase Usage
12.	Scr.& Wash.A.#8 x 3/4 OHER	B	626456	-----	NO	YES	Reduce Usage
A 13.	Field Install.-Rr.Wdo. Defogger	M	-----	649356	-	-	Reference Dwg.

This Engineering Memo effective at approximately Chassis #12269,P.O. #567