

June 6, 1974

ENGINEERING MEMO #355

TO: Memo Distribution

FROM: C. Bland

SUBJECT: Courtesy Lamp

Due to General Electric's termination of the T4- $\frac{1}{2}$ Lamp, type # 551, a redesign of the Courtesy Lamp has been necessary.

This change will be made with a minimum of obsolescence.

Service will be affected in that the new Courtesy Lamp will not replace the old without a revision to the wiring. This revision requires that the present terminal be replaced with a #2962132 Female Tip Terminal.

Following is a complete list of parts affected:

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT: NEW FOR OLD	AVAIL. AFTER CHG	REMARKS
1	Lens A.-Courtesy Lamp Compl	M	645577	651910	No	No	Serv or Scrap
2	Lens A.-Courtesy Lamp	B	645578	651859	No	No	Serv or Scrap
3	Lens Body- Courtesy Lamp	F	644420	646744	No	No	Serv or Scrap Unbal. Stock
4	Clip- Courtesy Lamp	F	644421	-----	-	No	Serv or Scrap Unbal. Stock
5	Clip & Wire A.- Dome Lamp	F	-----	651861	-	Yes	New Part
6	Clip- Courtesy Lamp Ground	F	644422	-----	-	No	Serv or Scrap Unbal. Stock
7	Clip- Dome Lamp	F	-----	2977087	-	Yes	New Part
8	Bulb- Miniature Lamp	B	626802	626936	No	Yes	Serv or Scrap Unbal Stock
9	Wire A.- Rear Dome Lamp	B	641403	Chngs "E & F"	No	Yes	Rework
10	Wire A.- Drivers Dome Lamp	B	641404	Chngs "B & C"	No	Yes	Rework
11	Cable A.- Roof & Dome Lamp	B	641405	Chngs "D & E"	No	Yes	Rework