

ENGINEERING MEMO #376

TO: MEMO DISTRIBUTION
 FROM: C. BLAND
 SUBJECT: SEAT BELT AND HARNESS ASSEMBLIES

At the request of Purchasing the Irvin Industries Inc. seat belt system will be replaced by a Hamill Manufacturing Company seat belt system.

Although the belts look similar, the blade portion of one belt system will not fit properly into the buckle of the other system. This will affect service in that old and new parts are not interchangeable.

This change will be made with a minimum of obsolescence.

Following is a complete list of parts to be affected.

| ITEM | NAME | B or M | OLD PART NUMBER | NEW PART NUMBER | INT. NEW FOR OLD | AVAIL. AFTER CHG. | REMARKS |
|------|--|--------------|-----------------------|-----------------------|---------------------------|-------------------------|----------------|
| 1 | Belt&Retractor A-RR. St. | B | 651912 | 653191 | No | No | Serv. or Scrap |
| 2 | Belt&Retractor A-RR. St. Fwd | B | 651913 | 653192 | No | No | Serv. or Scrap |
| 3 | Belt Asm - RR. St. Fwd | B | 651914 | 653193 | No | No | Serv. or Scrap |
| 4 | Belt Asm - RR. Seat | B | 651917 | 653194 | No | No | Serv. or Scrap |
| 5 | Harness Asm - Frt. St. L.H. | B | 651915 | 653195 | No | No | Serv. or Scrap |
| 6 | Harness Asm - Frt. St. R.H. | B | 651940 | 653196 | No | No | Serv. or Scrap |
| 7 | Plug - Retractor Cover | B | 651779 | - - - | - | No | Serv. or Scrap |
| 8 | Sleeve-Seat Belt | B | 646599 | Chg"A" | - | - | Revise Usage |
| 9 | Screw&Wa.Asm #8x3/4 OHCR Tapp #6 HD | B | 626456 | - - - | - | - | Revise Usage |
| 10 | Belt Guide-Seat | F | 646652 | - - - | - | - | Serv. or Scrap |