

August 27, 1979

ENGINEERING MEMO #410

TO: Memo Distribution

FROM: C. Bland

SUBJECT: WINDSHIELD DEFROSTING & DEFOGGING SYSTEM

To improve the Windshield Defrosting & Defogging System on Diesel engine cars the air flow will be increased to the windshield.

This change will be made on the first production of Diesel engine cars and incorporated into the gasoline cars with a minimum of obsolescence.

Service will be affected in that some new parts are not interchangeable with old parts.

Following is a complete list of parts to be affected.

REVISIONS			
DATE	ITEM REV & PAGE NO.	DATE	ITEM REV & PAGE NO.
10-9-79	Items 11-16 Added		
11-12-79	Rev P.2		
11-15-79	Rev P.2		

ENGINEERING MEMO # 410 (Cont'd)

ITEM	NAME	B OR M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Panel-Instrument	M	646508	Chg H	YES	NO	Serv or Scrap
2	Duct & Gskt A-Defroster	M	639233	653547	NO	NO	" " "
3	Gasket-Defroster Duct	B	634107	Chg E	YES	NO	" " "
4	Duct A-Defroster	B	653128	653546	NO	NO	" " "
5	Hose-Defroster 2-1/2	B	653110	- - -	-	-	" " "
6	Hose-Defroster 3"ID	B	- - -	653548	-	YES	New Part
(A)7	Rivet 3/16 POP	B	626790	- - -	-	YES	No Change Increase Usage
8	Housing-Dash Mt Heater	M	634294	Chg E	NO	NO	Rework
9	Grommet-Defroster Hose	B	632088	- - -	-	-	Serv or Scrap
10	Pad A-Instrument Black	B	645334	Chg C	YES	NO	Rework
(B)11	HEATER ASM-DASH MT	M	641451	Chg E	NO	YNO	Serv or Scrap
(B)12	HOUSING ASM-DASH MT HEATER	M	639810	Chg B	NO	NO	Serv or Scrap
13	CLAMP ASM-3.19 "HOSE-TYPE D"	B	451229	- - -	-	-	Reinstate
(B)14	GASKET-DASH MTG-HTR HSG (DOOR)	B	634325	- - -	-	NO	Serv or Scrap
15	FOAM TAPE-1/8 x 1/2	B	- - -	MH-144	-	-	New Part
(B)16	DUCT & HOSE ASM-DEFROSTER	M	639232	653200	NO	NO	Serv or Scrap