

Unified victor Integration Software for ThyssenKrupp Elevator Integration version 2.40.1061.0 Release Notes

Version A0 November 2015

This document provides important information about the Unified (victor/ C•CURE 9000) Integration Software for ThyssenKrupp Elevator Integration. Please read this file before installing the product.

Product: Unified (victor/ C•CURE 9000) Integration Software for ThyssenKrupp Elevator Integration

- Release: 4.8
- ThyssenKrupp Integration Software: V2.40.1061.0

Contents

1.	Overview	2
	Features	
3.	Hardware Requirements	2
	Software Requirements	
5.	Qualified Operating Systems	2
	Contents	
7.	Pre-Installation	3
8.	Installation	3
_	Post-Installation	_
	Issues and Limitations	
	nd of Release Notes	

8200-1147-41 A0

Overview

The ThyssenKrupp Elevator System Integration with the Unified Application Server (with C•CURE 9000 and victor) provides security to particular landings (floors) in a multi-level building by ensuring that only those authorized may go to a particular landing, or exit on that landing. Access to a particular landing is determined through a swipe of a card to a card reader outside of the elevator. The card reader accesses the personnel privilege assigned to a specific ThyssenKrupp Elevator access configuration.

2. Features

The Unified Application Server integration software for ThyssenKrupp Elevator offers the following features:

- Secured access to particular floor of a multi-level building by ensuring that only those authorized may go to a particular floor or exit on that floor.
- Schedule-based floor access for all personnel.
- Communication status of elevator systems.
- Journaling and reporting of floor selection by personnel.
- Remote Monitoring is supported using Activity Viewer.
- Schedule actions to secure or unsecure floors.
- Exemption Group can access Secured Floors.

3. Hardware Requirements

ThyssenKrupp Elevator Integration has the same hardware, software, and disk space requirements as the Unified Application Server; if the target computer can install Unified Server, then it satisfies ThyssenKrupp Elevator Integration requirements.

4. Software Requirements

The Unified Server Integration software for ThyssenKrupp Elevator requires the following software versions:

C•CURE 9000 Clients: v2.42victor unified client: v4.8

NOTE: The ThyssenKrupp Elevator Integration server components cannot be installed on a victor Application Server MAS.

Close any running applications to avoid installation problems.

NOTE: Client workstation(s) requiring ability to setup the ThyssenKrupp Elevator objects will need to install the ThyssenKrupp Elevator Integration client components.

5. Qualified Operating Systems

All Operating systems supported by victor are supported by this driver. Refer to victor product data sheets.

2 8200-1147-41 A0

6. Contents

The unified (victor/ C•CURE 9000) Integration Software for ThyssenKrupp Elevator contains the following:

File	Description
ThyssenKrupp_Integration.exe	ThyssenKrupp Integration software setup file

7. Pre-Installation

To perform the installation on the victor Application Server:

- You must have appropriate Windows permissions. You must have membership in the local Administrators group, or equivalent privileges. See the Microsoft Operating System document or system administrator for more information.
- 2. You must have installed unified Application Server V4.8 and licensed with the following option(s):
 - Unified Application Server (C•CURE -VICTOR)
 - ThyssenKrupp

To perform the installation on the client(s):

- 1. You must have appropriate Windows permissions. You must have membership in the local Administrators group, or equivalent privileges.
 - See the Microsoft Operating System document or your system administrator for more information.
- 2. You must have installed Administration Workstation
- 3. You must have installed Monitoring Station
- 4. You must have installed victor client

8. Installation

Perform the following steps to install the unified victor/ C•CURE 9000 Integration Software for ThyssenKrupp Elevator:

SERVER

Note: You must install the ThyssenKrupp Elevator Integration in the same folder as victor/ C•CURE 9000. Also, you must have administrator privileges to do the install; otherwise the system displays the error message: "The system administrator has set policies to prevent this installation."

- 1. Double-click the ThyssenKrupp Integration.exe file.
- 2. The installation program determines if the correct version of victor/ C•CURE 9000 are installed on your system, and if it is not, a message is displayed stating that a supported version of victor/ C•CURE 9000 is needed.
- 3. The Install Wizard begins installing the software, and the ThyssenKrupp Elevator Integration **Welcome** screen appears.
- Click Next and follow the Install Wizard prompts.
 NOTE: On License Agreement, be sure to select "I accept the terms in the license agreement" before clicking Next.
- 5. Click **Finish** to complete the Installation.

8200-1147-41 A0 3

Remote Client(s)

- 1. Double-click the ThyssenKrupp Integration.exe file.
- 2. The installation program determines if the correct version of victor/ C•CURE 9000 are installed on your system, and if it is not, a message is displayed stating that a supported version of victor/ C•CURE 9000 is needed.
- 3. The Install Wizard begins installing the software, and the ThyssenKrupp Elevator Integration Welcome screen appears.
- 4. Click **Next** and follow the Install Wizard prompts.
 - **Note**: On License Agreement, be sure to select "I accept the terms in the license agreement" before clicking **Next**.
- 5. Click **Finish** to complete the Installation.

9. Post-Installation

- 1. Launch the Server Configuration Application (Run as administrator) from the Start Menu via either:
 - Start > All Programs > Tyco
- 2. Restart the CrossFire services:

On the Services tab:

- a. Click **Stop Service** for the Crossfire Framework Services and wait for all Services to show Status: Stopped
- b. Click **Start Service** for the Crossfire Framework Services and wait for it to show Status: Running
- c. Click **Start Service** for the Crossfire Server Component Framework Services and wait for it and others to show Status: Running
- d. On the Server Components tab:
- e. Click **Start Service** for the "ThyssenKrupp Elevator Driver Service" and wait for it to show Status: Running
 - Start > All Programs > victor

10. Issues and Limitations

- Upgrade of this driver is supported using User Account which was used to install earlier version of ThyssenKrupp Elevator integration.
- For a valid card swipe landing matrix for all clearances associated with this personal will be sent to Elevator system. This includes expired and inactive clearances.
- ThyssenKrupp Elevator Integration will not consider the following access control functions:
 - o Antipassback
 - o Area Lockout
 - o Area Configuration
 - Occupancy Counting
 - Intrusion Zones
- Occasionally, Kiosk status message is displayed multiple times on Monitoring Station.
- When Elevator System is enabled, it will take few minutes for the associated Kiosks to show online status.
- ThyssenKrupp Elevator integration is not supported on Remote client of MAS (C•CURE 9000 and victor)
- On Microsoft Windows 2008 R2 Server when the user changes the time zone from non DST to DST time zone and vice-versa exception messages are logged.

4 8200-1147-41 A0

- Marathon Redundancy solution is not supported.
- When victor is upgraded from 4.7.1 to 4.8, the integration service will be missing.
 Resynchronize the ThyssenKrupp integration driver from "Programs and Features" or run the integration installer and click Resynchronize.

End of Release Notes

The trademarks, logos, and service marks displayed on this document are registered in the United States [or other countries]. Any misuse of the trademarks is strictly prohibited and Tyco Security Products will aggressively enforce its intellectual property rights to the fullest extent of the law, including pursuit of criminal prosecution wherever necessary. All trademarks not owned by Tyco Security Products are the property of their respective owners, and are used with permission or allowed under applicable laws.

Product offerings and specifications are subject to change without notice. Actual products may vary from photos. Not all products include all features. Availability varies by region; contact your sales representative.

© 2015 Tyco Security Products. All rights reserved.

8200-1147-41 A0 5