

OGIO® Fuse Polo. OG131



Only OGIO can fuse ultramodern welding details with comfortable stretch for a sharp, distinctive look.

- 5.9-ounce, 96/4 poly/spandex pique with stay-cool wicking technology
- OGIO heat transfer label for tag-free comfort
- Self-fabric collar
- OGIO stretch neck tape
- Black reflective, welded left chest pocket
- Set-in, open hem sleeves
- Black reflective O heat transfer on left sleeve
- Black reflective, welded 3-button placket with dyed-tomatch, debossed O buttons
- Embossed OGIO on back right shoulder
- Black reflective, welded side vents



front



back

HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SIZE CHART

		XS	S	М	L	XL	2XL	3XL	4XL
Che	est	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Pocl	ket Height	4 1/4	4 1/4	4 1/2	4 1/2	4 1/2	4 1/2	4 1/2	4 3/4
Pocl	ket Width	4	4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/2

COLOR INFORMATION

PMS NTR BLACK PMS 7686C



Blacktop





PMS 425C



PMS 7427C

Signal Red