

2D bar code scanner programming sheet  
Make sure scanner is fully charged (if wireless)

1. Restore factory defaults
2. Wait for scanner to reboot (~10 seconds)
3. Scan the rest of these bar codes in order



---

Send ENTER key after good scan  
Scan the following 3 bar codes in order:

