

New bar code scanner sheet

Robert Stark to: hdssupport, Julie Mossberg, Mike Tankersley

06/12/2014 03:01 PM

OK, folks.

Here is the new programming sheet for the Motorola/Symbol barcode scanners (wired and wireless) so they will read the DataBar Limited barcodes that are starting to show up on some products. If, after following these instructions, a wireless scanner will still not read a DBL barcode, remove the battery (see attached instructions), hold the trigger for 30 seconds, replace the battery, dock the scanner, wait 5 seconds, and start the sheet over again. I've included a sample sheet of DBL barcodes so you can check your scanner after programming. I am going to include the programming document on the customer systems image the next time the images are refreshed. In the meantime I suggest you copy it to any CS machines you see fit. NOTE: OBMini will not scan a DBL barcode at this time. That is still being looked into.

Please let me know if you have any questions.



BarCodeScannerProgrammingSheet.pdf



LS4278_Battery_Replacement_and_Reconditioning.pdf



DataBarLimitedExampleBarcodes.pdf

Robb Stark
Systems Support
H. D. Smith
3201 West White Oaks Drive Suite 400
Springfield IL 62704
217-753-3770 x8839
rstark@hdsmith.com
Helping You Care For Your Community