









SUPER COACHVAC® HEPA/SUPER QUARTERVAC® HEPA

Specs

Motor: 1188 watt/9.9 amp

Airflow: 150 CFM Static Lift: 100"

Super CoachVac HEPA Sound Level: 66 dBA

Weight: 11 lbs. Capacity: 10 qt./11 L

Four Level® Filtration w/HEPA: 1190 sq. in. total area

Super QuarterVac HEPA Sound Level: 67 dBA

Weight: 10 lbs. Capacity: 6 qt./6.6 L

Four Level® Filtration w/HEPA: 845 sq. in. total area

*All specs are based on motor specs.

Includes: a 11/2" static-dissipating vacuum hose, a 50' extension cord and two Intercept Micro Filters.









POWERFUL

SUPERIOR

ADVANCED

Warranty*

3 years on parts, labor and motor. Lifetime on body.

*see Owner's Manual for complete warranty details.

Advantages

Super CoachVac HEPA and Super QuarterVac HEPA, with HEPA Level Filtration, are designed to handle high square-footage areas that require the utmost cleanliness. A high-powered motor combined with Four Level Filtration and a 10 quart filter trap more dust with less downtime.

Removes substantially more soil from commercial carpet and is more than 3 times faster than traditional uprights.

HEPA filter works in concert with ProTeam's advanced Four Level Filtration system (including organically treated Intercept Micro Filters) to capture 99.97% of airborne particles .3 micron or larger which meets HEPA filtration levels.

The Super CoachVac HEPA and Super QuarterVac HEPA have earned the Gold Seal of Approval/Green Label from the Carpet and Rug Institute (CRI), signifying the vacuum system meets higher standards for carpet cleaning effectiveness and Indoor Air Quality.

Meets the requirements of the U.S. Green Building Council's LEED rating system for Green Cleaning – Sustainable Cleaning Equipment.

Utilizes mountaineering-style backpack technology to carry the vacuum comfortably and ergonomically across the hips. Backpack vacuums are proven to clean more area in less time and with less operator fatigue.

Integrated tool belt keeps accessory tools within your grasp.

Includes a thermal protector shut-off switch that prevents the motor from overheating due to a full filter or obstruction within the vacuum.





CANISTERS • BATTERY • WET/DRYS • UPRIGHTS **BACKPACKS** • AIR MOVERS • HIPSTYLE • FILTERS

www.pro-team.com

866.888.2168





