
# **SCHONBEK**<sup>®</sup>

T HIS DESIGN IS THE PROPRIETARY TRADE DRESS/TRADEMARK OF SCHONBEK WORLDWIDE LIGHTING INC.




		son who o <sub>l</sub> llowing in
CODE	#	F
PACKER	#	S
ORDER	#	S




## **SCHONBEK®**


#### Follow steps in exact order Save this trim diagram for future reference

IMPORTANT pens carton should record the formation for future service. Four-digit number on outside of carton. See crystal package label. See crystal package label.





PAGE 7




3783-\_\_\_TK

PAGE 6

3783-\_\_\_\_TK

### For easy removal of crystal from bubble pack, please cut along pouches on the inside of the seam. Gently remove crystal from the side of the pouch.



### **NOTE: Work on one** crystal set at a time. Follow the black line from top to bottom according to the numbered steps on the trim diagram.

