

Firestone Tire Recall

More than 100 deaths...


More than 250 injuries...

More than 1000 complaints...

Between 1989 and 1999, Bridgestone/Firestone received at least 1,096 consumer complaints of tread separations on Firestone radial ATX and ATX II tires.

Bridgestone/Firestone has consistently insisted on keeping these documents confidential.

In October 2000, they were finally released.



Copies of these internal Bridgestone/Firestone documents are available to ATLA members on a CD-Rom from the ATLA Exchange. You can contact the Exchange at 1-800-344-3023, or email exchange@atla.org.