

10

**Watchman**[illegible][illegible]

Reason for special inspection ? \_\_\_\_\_

Supervisory Certification Jamie Keane

10

Page 1 of 1

W.O Number 2122957 /

To Colin Spence

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED

Yes ☒ visually only

Yes \_\_\_\_\_ NO   X  

Yes \_\_\_\_\_ NO X

100

T Schiel

Supervisory Certification James Leavelle

OK

Page 1 of 1

W.O Number 2122048 /

To CAMDEN

[illegible]

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?  
Yes ☐ NO ☒

**SPECIAL INSPECTION** Yes \_\_\_\_\_ NO ☒

Reason for special inspection ? \_\_\_\_\_

T Schisler

tion Jamun Seava



**( Please Print)**

W.O Number 2123004

**To**

1. 1994년 12월 15일

## Restraining Rail

1	Joint Mismatch 1/4" on Side of Restraining Rail. Also Joint Loose.
---	--

2 Joint Mismatch 1/4" on side of Restraining Rail. ALSO Joint Loose.

Yes                     

**Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?**

NO                     

Reason for special inspection ? \_\_\_\_\_

Track Inspector Signature  
*Arthur R. Lethro*

on Jannet Ruan



Figure 1

Page of

W.O Number 21220511

[illegible]

### Supervisory Certification

*Catherine Kabetka*

Supervisory Certification Jamun Ram

OK  
Feb 4

Page 1 of 1

/atchman

To LUTHERVILLE

W.O Number 2120630

[illegible]

Yes VISUAL ONLY  
X

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?  
Yes \_\_\_\_\_ NO ☒

SPECIAL INSPECTION Yes \_\_\_\_\_ NO 16

Reason for special inspection ? \_\_\_\_\_

**Track Inspector Signature**

T Schiele

### Supervisory Certification

on James R.

7

(Please Print)

W.O Number 21206077

[illegible]

Walter V. Bryant



7

Page 2 of 2

2120607

LINE

[illegible]

James R. ...

Walter W. Bryant





Page 1 of 2

/atchman

Linthicum

To

CPomWell

W.O Number

2115946

[illegible]

Yes ☒

**NO**

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?  
Yes ☐ NO ☒

SPECIAL INSPECTION Yes \_\_\_\_\_ NO ☒

Reason for special inspection ? \_\_\_\_\_

**Track Inspector Signature**

### Supervisory Certification

Walter W. B. Junt

OK.

Page 2 of 2

Inspected From

W.O Number 2115946

To

### How to use this book

Riding inspection - Track inspection completed  
No defects noted

Yes ☒

**NO**

Yes            NO            ☒

NO ✓

Reason for special inspection ? \_\_\_\_\_

### Supervisory Certification

Walter W. Byrd

n James R. Kear

# TRACK INSPECTION REPORTING FORM

Page of

/atchman

To Leontineum


W.O Number 2129283

[illegible]

Item	COMMENTS
------	----------

## Riding Inspection

Were Switch in the area of Inspected Yes \_\_\_\_\_ NO           

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?  
 Yes NO 

**SPECIAL INSPECTION** Yes \_\_\_\_\_ NO ✓

Reason for special inspection ? \_\_\_\_\_

**Track Inspector Signature**

### Supervisory Certification

on Janner Brewer