




8	7	6	5
REPLACEMENT PART NUMBER	FACTORY INSTALLED PART NUMBER	DESCRIPTION	
RH-KIT-DD-LATCH	-	PKG, TURN HDL, ROTARY, STL, 2PT LATCH DD	
-	3173	PKG, TURN HDL, STL, 2PT LATCH	
-	6864	PKG, ROTARY, BTM, RIGHT HAND, ROOF HATCH, GALV	
RH-KIT-DD-SSTLATCH	-	PKG, TURN HDL, ROTARY, SST, 2PT LATCH DD	
-	25005	PKG, TURN HDL, 2PT LATCH, SST	
-	4079	PKG, 2PT LATCH, SST	







FACTORY INSTALLED VIEW



ZPS REPLACEMENT PART VIEW



SST REPLACEMENT PART VIEW



DOUBLE DOOR LATCH

Babcock-Davis
Always right there.
 9300 73rd Avenue North
 Brooklyn Park, MN 55428

TITLE: Roof Hatch, Equipment Access,
 48x48, Dbl Dr,
 Alum, Mill, Sngl Wall Curb,

NAME	DATE	SIZE	DWG. NO.	REV
DRAWN	DWO	3/27/13	B	RH-KIT-RETRO
RELEASED	ELW	4/10/2013		
				A

SHEET 3 OF 9