

GETZ MANUFACTURING

PART # 59341

DCX-20 REFILL SYSTEM

DCX-20 OPERATING INSTRUCTIONS

TO LOAD DCX-20

1. Remove DCX “V” clamp from DCX-20.
2. Remove the lid from the chemical pail.
3. Place DCX on top of pail & reattach “v” clamp ring.


NOTE: To load the DCX-20 with a 9 kg. or a 20 lb. plastic package of chemical, insert complete package inside the empty pail, draping top portion of package over the rim of the pail.

TO FILL A FIRE EXTINGUISHER

Secure the fire extinguisher to prevent possible toppling, then invert DCX on top of the extinguisher. Open valve. The chemical will flow like a fluid, filling the extinguisher in just seconds! When the extinguisher is full, the chemical will enter the clear lexan tube (in-line with vent return). Close valve. Let chemical settle out of lexan tube.

Now, remove the DCX-20 to an upright position.

ITEM	PART#	DESCRIPTION	UM	QPA
1	56207	WELDMENT DCX-20	EA	1.0000
2	53354	SEAL FOAM DELTA	EA	1.0000
3	51900	VLV BALL BR 3/4	EA	1.0000
4	53361	TUBE 1/2 X 5	FT	1.0000
5	53383	ELB PLAS 3/8 BARB X 1/4 NPT	EA	1.0000
6	53384	BARB PLAS 3/8 X 3/8 NPT	EA	1.0000
7	53382	HOSE 3/8 DELTA	EA	1.0000
8	53319	9413-2 DELTA	EA	1.0000
9	51624	PIPE ELB BR 1/4 ST	EA	1.0000
10	53343	CLAMP DCX-20	EA	1.0000
11	53434	SEAL RUBBER DCX-20	FT	2.5000
12	53315	9412 DELTA DCX-20	EA	1.0000
13	53413	CLAMP HOSE OETIKER 5/8	EA	2.0000
14	53401	PAIL PLAS 20 LB	EA	1.0000
15	MISC	WASHER	EA	1.0000
16	53337	SCREEN .027 X .25 X 6.25	EA	1.0000
17	53334	SCREEN .042 X .5 X 8.25	EA	1.0000



THIS DRAWING IS THE EXCLUSIVE AND CONFIDENTIAL PROPERTY OF GETZ MFG. IT SHALL NOT BE DUPLICATED, USED OR DISCLOSED TO OTHERS WITHOUT THE EXPRESS WRITTEN CONSENT OF GETZ MANUFACTURING.

REV.		DRAWING CHANGE		BY	ECN NO.	DATE	MATERIAL		FINISH	GETZ MANUFACTURING PEORIA, IL.		SHEET NO.	BIN NO.
FRAC. ± 0.20		2 PL DEC ± 0.10		3 PL DEC ± .003		TOLERANCES UNLESS OTHERWISE SPECIFIED		DWN BY R.D.M.	CK'D D.C.	DATE 8-20-01	1 OF 1		
TITLE DCX-20 COMPLETE										REV. *		59341	