



Xref C:\Cad1files\Drg. Frames\A3-Imp.dwg

06.12.00

SMOOTH & BRIGHT FINISH
THREAD FORM AS DRG.No. MS 0 - 8 F1

6