



911 / 912 / 918

FALCON®





24743429

R/V Trim
R/V Moldura
R/V Garniture


FOR TRIMS SHIPPING ON
OR AFTER 4-27-17

Installation Instructions
Instrucciones de instalación
Notice d'installation


- 1** Transfer $\mathbb{C}$ from device side to trim side of door
Transfiera $\mathbb{C}$ desde el lado del mecanismo
al lado de la moldura de la puerta
Transfert $\mathbb{C}$ du côté du dispositif vers
la garniture latérale de porte




- 2** Prepare Door
Prepara la Puerta
Préparer la Porte



- 3** Assemble Tailpiece
Arme la cola del pestillo
Assembler la pièce de raccordement



- 4** Install Tailpiece Guide into Exit Device Cam
Instale la guía de la cola del pestillo en la cámara del dispositivo de salida
Installer le guide de la pièce de raccordement dans la caméra de l'appareil de sortie



Customer Service Servicio al cliente Service à la clientèle
1-877-671-7011 www.allegion.com/us

ALLEGION®

© Allegion 2017
Printed in U.S.A.
24743429 Rev. 04/17-d

5

If Necessary, Rehand Trim
De ser necesario, ajuste la moldura
Réutiliser la garniture si nécessaire

912L (shown / se muestra / illustré)
912L-BE
912L-NL

LHR

LHR

RHR

Outside
Exterior
Extérieur

RHR

Loosen set screw
Afloje el tornillo prisionero
Desserrez la vis pression

Outside
Exterior
Extérieur

19-V-RHR

19-R all / todos / tous
19-V-LHR

Peg must sit between fork of tailpiece cam
La clavija debe colocarse entre la horquilla de la leva de la cola del pestillo
Le tenon doit se trouver entre la fourche de la came de la queue de pêne

Peg must sit between
fork of tailpiece cam
La clavija debe colocarse
entre la horquilla de la leva
de la cola del pestillo
Le tenon doit se trouver
entre la fourche de la
came de la queue de pêne

911K (shown / se muestra / illustré)
911K-BE
911K-NL

Outside
Exterior
Extérieur

19-R all / todos / tous
19-V-LHR

19-V-RHR

Peg must sit between fork of tailpiece cam
La clavija debe colocarse entre la horquilla
de la leva de la cola del pestillo
Le tenon doit se trouver entre la fourche
de la came de la queue de pêne

912L-DT

RHR

LHR

6

If Necessary, Install Cylinder
De ser necesario, instale el cilindro
Installer le cylindre si nécessaire

1 1/8-1 1/4"
(29-32 mm)

7

Return to
Device Instructions
Regrese a Instrucciones
del mecanismo
Retour vers les instructions
du dispositif



23834765

911K / 912L



FALCON®

Trim Tailpiece Assembly



Installation Instructions

19-R/V ONLY READ THIS FIRST

1 Choose Correct Tailpiece





The RHR version of this tailpiece type has a dimple between the 2 holes






2 Assemble Tailpiece

19-R





19-R-RHR






19-R-LHR

19-V



19-V-RHR



19-V-LHR

Customer Service

1-877-671-7011 www.allegion.com/us



© Allegion 2014
Printed in U.S.A.
23834765 Rev. 01/14-b