



## Gap Solution for Excessive Fire Door and Frame Clearance—45 Minute

UL Certified Solution for Fire doors with Excessive clearance between door and frame over 1/8", up to 5/16"

Requires installation of ALL components below

### Steel Stop Extender




9945

16 Gauge, Gray Primer Finish

Furnished with #10 X 1" TEK SMS  
Available in 36", 48", 84", 96" lengths

Patent No.: US9,273,510B2

### NGP-Edge® Intumescent Seal with PVC cover



9400 Gray  
9400DKB Brown

Available in 36", 48", 84" and 96" lengths

Self-Adhesive  
A95-Microbial

### Self-Adhesive TPE Seal




5075B Brown  
5075C Charcoal  
5075CL Clear



Available in 36", 48", 72", 84", 96" and 108" lengths

45 minute rated UL Certified Miscellaneous Fire Door Accessory UL10B and UL10C wood or hollow metal fire doors


An NGP strike shim 9275 or 9225 is also required for proper latchbolt engagement



**Strike Shims — 45 Minute**  
9275 - Fits 4-7/8" ASA Strike Plate  
9225 - Fits 2-3/4" T Strike Plate



9275  
Gray Paint finish



9225  
Gray Paint finish

UL Certified Miscellaneous Fire Door Accessory for excessive door and frame clearances, measuring up to 5/16"

45 minute rated UL10B and UL10C wood or hollow metal fire doors

