Phone: 800-647-7874 Fax: 800-255-7874

## **Smoke-Rated Astragal Sets**

Fire-rated Astragal Seals cannot replace any astragal required on the door by the door manufacturer to maintain its fire label. IBC, NFPA 80, NFPA105, NFPA 252 require the gap at the meeting edge between fire labeled doors must not exceed 1/8".

#6 x 3/4" Stainless Steel Sheet Metal Screws furnished. Screw holes are slotted for adjustment.

- clear В - gold

DKB - ďark bronze no suffix - mill epdm, silicone are gray neoprene is black

















