

Gap Solution for Excessive Fire Door Top Clearance — 90 Minute

UL Certified Solution for Fire doors with Excessive Door Top Clearances up to 1/2"

NGP-Edge® Intumescent Door Cap

Patent Pending

9990

UL Certified Miscellaneous Fire Door Accessory for excessive door top clearances, measuring up to 1/2"



90 minute rated UL10B and UL10C wood or hollow metal fire doors

Available in 36", 48" lengths

#6 x 3/4" Stainless Steel SMS furnished

Brushed stainless steel

Non-Handed

Product consists of:

- #304 Brushed Stainless Steel Flat Plate - pull side
- #304 Brushed Stainless Steel Intumescent Cap - push side
- #304 Brushed Stainless Steel End Caps

*No need to move hardware at the top of the door.
Works on doors with Parallel arm closers.*

