



9990

Fire Door Top Gap Solution — *Up To 90 Minutes*

PRODUCT CUT SHEET


**UL Certified for Door Top
Gaps — Measuring up to 1/2".**



- 90-Minute Rated— for use on UL10B and UL10C Wood or Hollow Metal Fire Doors
- No need to move hardware at the top of the door
- Works on doors with Parallel arm closers
- Patent Pending
- Available in 36" and 48" Lengths
- Brushed stainless steel
- Non-Handed

PRODUCT CONSISTS OF:

- + #304 Brushed Stainless Steel Flat Plate - Pull Side
- + #304 Brushed Stainless Steel Intumescent Cap—Push Side
- + #304 Brushed Stainless Steel End Caps
- + #6 x 3/4" Stainless Steel SMS Furnished



PROJECT:

SUBMITTED BY:

DATE:

NOTES:

NGP-FDA-9990-PCS-1119-A