


NOTES:

1. DO NOT PREDRILL MOUNTING HOLES.

REVISIONS

LTR	DESCRIPTION	DATE	CHECKED
—	NEW DWG.	5-31-95	<i>[Signature]</i>



Book No. Date Requested:
 This template is provided for use only on
 the job for which it was requested.
 Trimco/BBW reserves the right to make
 design changes without notice.

Trimco / BBW
 Triangle Brass Manufacturing Company, Inc.
 3528 Emery Street, P.O. Box 23277
 Los Angeles, CA 90023, USA

SCALE NONE

TITLE 4048
 CRASH CHAIN

PART NO

DRAWN BY T.A. 5-31-95

A DWG. NO. 11467