



CB19/CBH19/B19 CONTROL PANEL PARTS

MARCH 15, 1990



Revision Number - 2

*OPTIONAL PARTS-FIELD INSTALLED

| Callout | Name | Quantity | Description |
|---------|----------------------|----------|-------------|
| | Cat #: Model/Part #: | 1 | |

BLOWER PARTS

| Callout | Name | Quantity | Description |
|---------|---|----------|-------------------------------|
| | PLATE-CUTOFF Cat #: 46G30 Model/Part #: LB-15558D | 1 | PLATE-CUT OFF (12 x 9) |
| | ARM-MOTOR MTG Cat #: 92G34 Model/Part #: LB-59076CA | 3 | MOTOR FRAME SECTION S.A. |
| 35 | HOUSING-BLOWER Cat #: 38H06 Model/Part #: LB-78749CF | 1 | BLOWER HOUSING |
| 36 | MOTOR-BLOWER Cat #: 81G51 Model/Part #: 81G5101 | 1 | "1/2HP,825RPM,208-230/60/1" |
| 36 | MOTOR-BLOWER Cat #: 86G44 Model/Part #: 86G4401 | 1 | "1/2HP,825RPM,460/60/1" |
| 38 | WHEEL - BLOWER Cat #: 21772 Model/Part #: P-5-223 | 1 | "1/2""BORE,12-5/8"" X 9-1/2"" |
| C1 | CAPACITOR Cat #: 53H13 Model/Part #: 39H6401 | 1 | "20MFD,370VAC(208/230/460V)" |

CABINET PARTS

| Callout | Name | Quantity | Description |
|---------|---------------|----------|---------------|
| | SPACER-FILTER | 2 | FILTER SPACER |

| Callout | Name | Quantity | Description |
|----------------|--|-----------------|------------------------|
| | Cat #: 52H64 Model/Part #: LB-82097C | | |
| | GUIDE-FILTER Cat #: 52H65 Model/Part #: LB-82098C | 2 | FILTER GUIDE |
| 1 | CAP-CABINET Cat #: 66H41 Model/Part #: LB-58492CC | 1 | CAB. CAP SA - INSUL |
| 2 | PANEL Cat #: 55H78 Model/Part #: LB-79026CB | 1 | PLUMBING |
| 3 | PANEL Cat #: 66H42 Model/Part #: LB-58493CE | 1 | BLOWER |
| 4 | PANEL Cat #: 55H77 Model/Part #: LB-79025CB | 1 | PLUMBING |
| 5 | WRAPPER Cat #: 62H78 Model/Part #: LB-58486CC | 1 | RIGHT SIDE |
| 6 | WRAPPER Cat #: 66H43 Model/Part #: LB-58490CC | 1 | LEFT SIDE |
| 7 | PANEL Cat #: 55H66 Model/Part #: LB-58491CC | 1 | REAR |
| 8 | PANEL Cat #: 55H42 Model/Part #: LB-58495CC | 1 | SECURING |
| 9 | SHIELD-DRIP Cat #: 66H44 Model/Part #: LB-62848C | 2 | DRIP SHIELD |

COOLING PARTS

| Callout | Name | Quantity | Description |
|----------------|---|-----------------|-----------------------|
| | VALVE-EXPANSION Cat #: 43G02 Model/Part #: 43G0201 | 1 | (TXV UNITS) |
| | FUSE Cat #: 71G35 Model/Part #: 71G3501 | 1 | "N3 TYPE,3.5AMP,125V" |
| | CAP-SEAL Cat #: 86G97 Model/Part #: 86G9701 | 1 | CAP-PLASTIC SEAL |
| | SEAL-COIL Cat #: 66H48 Model/Part #: LB-58722C | 2 | TOP |

| Callout | Name | Quantity | Description |
|----------------|--|-----------------|----------------------------|
| | SUPPORT-COIL Cat #: LB-58723DA Model/Part #: LB-58723DA | 4 | SUPPORT-COIL |
| | HOSE-DRAIN Cat #: 17H55 Model/Part #: LB-59267D | 1 | HOSE-DRAIN |
| | SEAL-COIL Cat #: 51J84 Model/Part #: LB-62847C | 1 | BOTT(TXV UNITS) |
| | ADAPTER Cat #: 15J51 Model/Part #: LB-82210DA | 1 | LIQUID LINE ASSY |
| 10 | COIL-INDOOR Cat #: 29H76 Model/Part #: LB-81688CAC | 1 | W/MANIFOLD(FOOTNOTE 1) |
| 12 | PAN-DRAIN Cat #: 85G03 Model/Part #: LB-58245C | 1 | DRAIN PAN |
| 15 | DISTRIBUTOR ASSY Cat #: 10H77 Model/Part #: LB-61742CD | 1 | DIST ASSY |
| 17 | ADAPTER Cat #: 18J59 Model/Part #: 18J5901 | 1 | (TXV UNITS) |
| 17 | ADAPTER Cat #: 71G09 Model/Part #: 71G0901 | 1 | ADAPTOR |
| 20 | SEAL-COIL Cat #: 54J18 Model/Part #: LB-78924C | 1 | FRONT(TXV UNITS) |
| 20 | SEAL-COIL Cat #: 66H46 Model/Part #: LB-82293C | 1 | REAR |
| 21 | RESTRICTOR Cat #: 71G05 Model/Part #: 71G0501 | 1 | RESTRICTOR |
| 23 | RETAINER-PAN Cat #: 61H93 Model/Part #: LB-62852C | 1 | RETAINER PAN |
| 25 | SEAL-COIL Cat #: 66H47 Model/Part #: LB-82252C | 2 | FRONT |
| K1 | RELAY Cat #: 66C67 Model/Part #: P-8-10283 | 1 | "ID BLOWER,DPDT,24V(230V)" |
| K2 | RELAY Cat #: 66C67 Model/Part #: P-8-10283 | 1 | "ID BLOWER,DPDT,24V(230V)" |

| Callout | Name | Quantity | Description |
|----------------|--|-----------------|---------------------------------------|
| T1 | TRANSFORMER Cat #: 65G49 Model/Part #: 65G4901 | 1 | "208/230V PRI,24V SEC,70VA W/FUSE" |
| T1 | TRANSFORMER Cat #: 65G50 Model/Part #: 65G5001 | 1 | "480V PRI,24V SEC,70VA,W/FUSE" |
| TB1 | BOARD-TERMINAL Cat #: 78H59 Model/Part #: 78H5901 | 1 | TERMINAL BOARD |
| TB2 | BLOCK-TERMINAL Cat #: 71G38 Model/Part #: 71G3801 | 1 | LOCATED CAP CABINET |

Note:

Note1: WHEN REPLACING COIL, IT WILL BE NECESSARY TO REMOVE RESTRICTOR (KEY #21) FROM OLD COIL FOR USE IN THE NEW COIL, AS THIS PART IS NOT INCLUDED IN REPAIR COIL PACKAGE.