


CB29M—CONTROL PANEL PARTS

NOVEMBER 27, 1995





Revision Number - 1

BLOWER PARTS

Callout	Name	Quantity	Description
	SCREW-MTR MTG Cat #: 49L9602 Model/Part #: 49L9602	3	(FOOTNOTE 2)
	BAND-MOTOR Cat #: 62A57 Model/Part #: 62A5701	1	(FOOTNOTE 2)
	WHEEL-BLOWER Cat #: 40F86 Model/Part #: LB-29333BBM	1	BLOWER WHEEL (after 7/2003)
	HARNESS-WIRING Cat #: 64K20 Model/Part #: LB-74239	1	BLOWER MOTOR (208/230V & INT)
	PLATE-CUTOFF Cat #: 34L42 Model/Part #: LB-88708	1	CUTOFF PLATE
	HARNESS-WIRING Cat #: 27L51 Model/Part #: LB-89757	1	BLOWER MOTOR (460V)
33	ARM-MTR MTG KITFRAME SECTION (FS) BRACKE Cat #: Model/Part #:	1	
33	ARM-MOTOR MTG Cat #: 71M17 Model/Part #: LB-101207B	3	(FOOTNOTE 2)
35	HOUSING-BLOWER Cat #: 53K63 Model/Part #: 53K6301	1	BLOWER HOUSING S.A.
36	MOTOR-BLOWER Cat #: 18J96 Model/Part #: 18J9601	1	3/4HP, 1075 RPM, 208-230/60/1
36	MOTOR-BLOWER Cat #: 25J43 Model/Part #: 25J4301	1	3/4HP, 1075 RPM, 460/60/1 (460V)
36	MOTOR-BLOWER Cat #: 71J96 Model/Part #: 71J9601	1	1/2HP, 900 RPM ,220-240/50/1 (INT)
38	WHEEL-BLOWER Cat #: 10G44 Model/Part #: LB-29333BBP	1	WHEEL-BLOWER (before 7/2003)
C4	CAPACITOR-RUN Cat #: 22W80 Model/Part #: 100600-03	1	10MFD, 370VAC (INT)
C4	CAPACITOR	1	10MFD, 370VAC

Callout	Name	Quantity	Description
	Cat #: 39H61 Model/Part #: 39H6101		
C4	CAPACITOR-BLR MTR Cat #: 39H69 Model/Part #: 39H6901	1	10MFD, 440VAC (460V)

CABINET PARTS

Callout	Name	Quantity	Description
	FILTER-AIR 20" X 20" X 1" Cat #: Model/Part #:	1	
	CLIP-FILTER Cat #: 49K46 Model/Part #: 49K4601	3	CLIP-FILTER
	KIT-HARDWARE Cat #: 97M37 Model/Part #: LB-110418A	1	PKG OF 10 FOR FILTER DOOR
	SPACER-FILTER Cat #: 43L91 Model/Part #: LB-74258	1	FILTER
1	CAP-CABINET Cat #: 72M09 Model/Part #: LB-107656K	1	TOP CAP
2	PLATE Cat #: 72M10 Model/Part #: LB-107656L	1	PATCH
3	PANEL Cat #: 72M11 Model/Part #: LB-107656M	1	BLOWER
4	PLATE Cat #: 72M04 Model/Part #: LB-107656E	1	PLUMBING
5	WRAPPER Cat #: 72M08 Model/Part #: LB-107656J	1	RIGHT
6	WRAPPER Cat #: 72M07 Model/Part #: LB-107656H	1	LEFT
7	WRAPPER Cat #: 72M13 Model/Part #: LB-107656P	1	REAR
8	PANEL Cat #: 72M06 Model/Part #: LB-107656G	1	FILTER ACCESS

COOLING PARTS

Callout	Name	Quantity	Description
	LIQUID LINE Cat #: 44L35 Model/Part #: 44L3501	1	SWEAT ASSY INCLUDES SCREEN
	WASHER KIT Cat #: 49J23 Model/Part #: 49J2301PR	1	PKG (12)
	HARNESS-WIRING Cat #: 78K52 Model/Part #: LB-74237	1	POWER (208/230- 460V & INT)
	HARNESS-WIRING Cat #: 32L79 Model/Part #: LB-74238	1	CONTROL (208/230V & INT)
	CHANNEL Cat #: 64K05 Model/Part #: LB-88628	1	DRAIN
	CHANNEL Cat #: 64K06 Model/Part #: LB-88651	2	CONDENSATE
	HARNESS-WIRING Cat #: 53L91 Model/Part #: LB-89758	1	P50 (460V)
	HARNESS-WIRING Cat #: 53L92 Model/Part #: LB-89759	1	CONTROL (460V)
	LIQUID LINE KIT Cat #: 69J46 Model/Part #: LB-95325A	1	INCL TEN LIQUID LINES (44L35)+ WASHERS&N
10	COIL-INDOOR Cat #: 57K57 Model/Part #: LB-90287E	1	W/ MANIFOLD & TXV
12	PAN-DRAIN Cat #: 93J59 Model/Part #: 93J5901	1	(HORIZONTAL)
12	PAN-DRAIN Cat #: 68K32 Model/Part #: LB-90788C	1	PAN-DRAIN
15	DISTRIBUTOR ASSY(FOOTNOTE 1) Cat #: Model/Part #:	1	
16	VALVE-EXPANSION Cat #: 56J20 Model/Part #: 37J6801	1	VALVE- EXPANSION/CHECK- R22
20	SEAL-COIL Cat #: LB-88615 Model/Part #: LB-88615	1	REAR
21	SEAL-COIL Cat #: 40W91 Model/Part #: 600580-01	1	FRONT-TOP

Callout	Name	Quantity	Description
22	SEAL-COIL Cat #: 40W92 Model/Part #: 600581-01	1	FRONT-BOTTOM
23	SEAL-COIL Cat #: 23M90 Model/Part #: LB-88432	1	TOP
K3	RELAY Cat #: 67K65 Model/Part #: 67K6501	1	ID BLR, DPDT, 24V (INT)
K3	RELAY Cat #: 69J57 Model/Part #: 69J5701	1	ID BLR,DPDT,24V
K3	RELAY Cat #: 69J58 Model/Part #: 69J5801	1	ID BLR,3PDT,24V (460V)
S51	SWITCH Cat #: 25J13 Model/Part #: 25J1301	1	DOOR INTERLOCK (460V)
T1	TRANSFORMER Cat #: 13H28 Model/Part #: 13H2801	1	208/240V PRI,24V SEC,70VA L/FUSE (P & T)
T1	TRANSFORMER Cat #: 51H79 Model/Part #: 51H7901	1	480V PRI, 24V SEC, 70VA, L/ FUSE (460V)
TB1	STRIP-TERMINAL Cat #: 18K71 Model/Part #: 18K7101	1	TERMINAL BLOCK

Note:

Note1: DISTRIBUTOR ASSEMBLIES ARE NOT SET UP AS A REPAIR PART. IF COIL HAS MULTIPLE LEAKS IN THE DISTRIBUTOR ASSEMBLY, THE COIL SHOULD BE REPLACED. Note2: IF THE MOTOR FRAME SECTION (FS) BRACKETS NEED REPLACING, ORDER THE FOLLOWING PARTS; BLOWER WHEEL, ARMS, BAND AND SCREWS. ON UNITS BUILT BEFORE 6/02, THE BLOWER HOUSING ALSO NEEDS TO BE REPLACED.