

Revision Number - 1

CABINET PARTS

Callout	Name	Quantity	Description
	SPACER-FILTER Cat #: 66H55 Model/Part #: LB-82094D	1	FILTER SPACER
	GUIDE-FILTER Cat #: 66H54 Model/Part #: LB-82096C	2	FILTER GUIDE
1	CAP-CABINET Cat #: 66H49 Model/Part #: LB-58492CD	1	CAB. CAP SA - INSUL
2	PANEL Cat #: LB-59989CC Model/Part #: LB-59989CC	1	PLUMBING
2	PANEL Cat #: 54K40 Model/Part #: LB-79027CE	1	PLUMBING(TXV UNITS)
3	PANEL Cat #: 55H39 Model/Part #: LB-58491CD	1	REAR
4	PANEL Cat #: 55H38 Model/Part #: LB-58486CD	1	RIGHT
5	PANEL Cat #: 66H52 Model/Part #: LB-58490CD	1	LEFT
6	PANEL Cat #: 34H81 Model/Part #: LB-58495CD	1	SECURING
6	PANEL Cat #: 30K92 Model/Part #: LB-58495CM	1	SECURING(TXV UNITS)
7	PANEL Cat #: 54K41 Model/Part #: LB-79024CD	1	PLUMBING(TXV UNITS)

COOLING PARTS

Callout	Name	Quantity	Description
	VALVE-EXPANSION Cat #: 56J20 Model/Part #: 37J6801	1	(TXV UNITS)
	HOSE-DRAIN Cat #: 17H55 Model/Part #: LB-59267D	1	HOSE-DRAIN

Callout	Name	Quantity	Description
	ADAPTER Cat #: 17H56 Model/Part #: LB-61604D	1	EXPANSION VALVE
	SUPPORT-COIL Cat #: LB-87378 Model/Part #: LB-87378	2	(TXV UNITS)
	SUPPORT COIL Cat #: LB-87637 Model/Part #: LB-87637	2	(TXV UNITS)
10	COIL-INDOOR Cat #: 14H47 Model/Part #: LB-81688CL	1	W/MANIFOLD (FOOTNOTE 1)
10	COIL-INDOOR Cat #: 96J39 Model/Part #: LB-87363J	1	W/MANIFOLD(TXV UNITS)
11	SEAL-COIL Cat #: LB-58751C Model/Part #: LB-58751C	2	FRONT & REAR
11	SEAL-COIL Cat #: 66H57 Model/Part #: LB-82295C	1	REAR(TXV UNITS)
12	PAN-DRAIN Cat #: 54H21 Model/Part #: LB-58619CC	1	DRAIN PAN S.A.
12	PAN-DRAIN Cat #: 35K29 Model/Part #: LB-87299C	1	(TXV UNITS)
13	SHIELD-DRIP Cat #: LB-59289C Model/Part #: LB-59289C	1	DRIP CHANNEL
13	SHIELD-DRIP Cat #: 17J79 Model/Part #: LB-64999	1	(TXV UNITS)
13	SHIELD-DRIP Cat #: 17J80 Model/Part #: LB-65000	1	(TXV UNITS)
15	DISTRIBUTOR ASSY Cat #: 10H76 Model/Part #: LB-61742CC	1	DIST ASSY
15	DISTRIBUTOR ASSY Cat #: 96J29 Model/Part #: LB-61742CG	1	(TXV UNITS)
17	ADAPTER Cat #: 71G09 Model/Part #: 71G0901	1	ADAPTOR
19	PAN-DRIP Cat #: 84H51 Model/Part #: LB-59288CA	1	DRIP PAN SA
19	PAN-DRIP	1	(TXV UNITS)

Callout	Name	Quantity	Description
	Cat #: LB-59288CC Model/Part #: LB-59288CC		
21	RESTRICTOR Cat #: 71G04 Model/Part #: 71G0401	1	RESTRICTOR
22	CAP-SEAL Cat #: 58114 Model/Part #: P-8-3187	1	CAP, BRASS
25	SEAL-COIL Cat #: LB-74089 Model/Part #: LB-74089	1	FRONT(TXV UNITS)

Note:

Note1: WHEN REPLACING COIL, IT WILL BE NECESSARY TO REMOVE RESTRICTOR (KEY #21) FROM OLD COIL FOR USE IN THE NEW COIL, AS THIS PART IS NOT INCLUDED IN REPAIR COIL PACKAGE.