


Humidifier Replacement Parts



Legacy Drum Model 65



Item	Qty. Req'd	GFI #	Part Description
1	1	7302	12853 Drum Assembly
2	1	7157	P188 Retainer Clip
3	1	7305	12855 Open Drum End
4	1	7306	12856 Drum Shaft
5	1	7312	65 - 5 Replacement Evaporator Sleeve 7" W, 5" I.D.
6	1	7304	12854 Closed Drum End
7	1	7307	12859 Cover Assembly (Including Window)
8	1	7308	12861 Window
9	1	7301	12852 Motor Mounting Plate
10	1	7113	727 - 40 Motor Assembly
12	1	7096	81 - 21 Float Valve Assembly
13	1	7076	747 - 11 Valve Washer
14	1	7123	727 - 8 Splash Guard
15	1	6005	975 - 6 Valve Shield
16	1	7122	727 - 24 Orifice Fitting
17	1	6004	975 - 1 Valve Seat
18	1	6026	P118 Cotter Pin
19	1	7097	81 - 11 Float Arm
20	1	7098	81 - 12 Float
21	1	6001	975 - 3 Orifice Nut
22	1	7309	12851 By - Pass Collar
23	1	7126	81 - 14 Valve Hole Cover
24	1	7300	12849 Humidifier Cabinet
25	2	7140	40 - 7 Speed Nut
26	2	7095	81 - 13 Thumb Screw
27	1	7310	12857 Water Pan
Parts Not Shown			
	1	7311	12863 5" By - Pass Tube Assembly
	1	7118	727 - 58 24V Transformer (12VA)
	1	8022	800 - UST Self - Tapping Saddle Valve Kit
	1	7078	747 - 38 Water Supply Tubing Kit
	1	7038	MHX3C Manual Control, Wall / Duct Mount Humidistat
	1	7053	WMH3 Wall Mount Housing
	1	8035	8035 Humidex Tablets

*NLA = No Longer Available

Humidifier Replacement Parts

1% 10 Days. Net 30 Days. F.O.B. Novi, Michigan \$3,000 Orders FFA

General Filters, Inc. 43800 Grand River Avenue Novi, Michigan 48375-1115 Toll Free (866) 476-5101 Fax (248) 349-2366 www.GeneralAire.com