

Ugly Mudder® glove care guide

Regular washing helps remove sweat, dirt, oils, and contaminants that can build up during the workday, and many PPE items can be easily washed right on site.

Washing instructions:

Hand wash only

Hand wash using mild semi-diluted cleaner and scrub until clean.

Rinse thoroughly.

Drying instructions:

- Hang to dry (indoors), do not tumble dry. Do not iron.
- Store in clean, dry conditions, away from direct sunlight or extreme temperatures.



Disclaimer:

Laundrying/washing HexArmor® hand and body protection is generally not recommended because it is not known if this will impact product performance. Performance retention after laundrying or washing is not guaranteed and is variable depending on the cleaning methods used, detergent type, and conditions the products were exposed to during use. HexArmor® products are not certified or tested for compliance after laundrying/washing. Laundrying/washing does not restore worn or damaged materials. Users must inspect PPE before each use and replace if performance is compromised. Continued use after laundrying/washing is at the user's own risk. For North American markets only.