

INDIVIDUAL PARTS		INDIVIDUAL PARTS		COMPOSITE PARTS	
C-13	Dome cover	SC-13C	Dial	C-5	Spindle assembly
HP-2	Shield (standard unit)	SC-15A	Set screw	C-50	Renewable seat socket wrench
HP-3	Shield (short unit)	SC-18	Lock nut	KIT-B	Washer and gasket kit
HP-4	Top cap	S2H-8D	Set screw	SC-2	Cap assembly
HP-5	Soap dish	SC-3	Renewable seat	SC-3	Renewable seat unit complete
HP-6	Nameplate	SC-7	Packing nut	HP-17ASB	Stop assembly
HP-7A	Screw	SC-9	Cold washer retainer		
HP-8	Shower head bracket	SC-10	Hot washer		
HP-10	Body cover	SC-10A	Screws		
HP-10A	O-ring	SC-11	Cold washer		
HP-14	Screw	SC-17	Packing		
HP-14A	Washer	SC-19	Cap gasket		
HP-14B	Star plastic anchors	SC-26	Limit stop with o-ring		
HY-1A	Piping assembly (standard unit)	4-231M	Super shower head		
HY-1B	Piping assembly (short unit)				
J-32B	O-ring				
RC-14	Handle				

Tools required for installation:

Slotted screwdriver, Phillips screwdriver, soldering equipment, adjustable wrench, channel lock pliers, hex socket keys (1/8" and 3/32"), electric drill with 1/4" drill bit, HY-50 screwdriver (provided)

CAUTION: Do not misplace vandal-proof screws (HP-7A) after removing from unit cover. Screws will be required to reinstall unit cover to piping assembly.

