

CITY OF SOMERVILLE, MASSACHUSETTS MAYOR'S OFFICE OF STRATEGIC PLANNING & COMMUNITY DEVELOPMENT KATJANA BALLANTYNE MAYOR

TOM F GALLIGANI JR EXECUTIVE DIRECTOR

PLANNING DIVISION HISTORIC PRESERVATION

ALTERATION OF A LOCAL HISTORIC DISTRICT (LHD) PROPERTY STAFF REPORT

Site: 77 Perkins Street

Case: HPC.ALT 2023.32

Applicant: Shane & Ryan Sullivan

Owner: Same as Applicant

Legal Ad: The Applicant seeks a Certificate of Appropriateness to replace wood windows.

HPC Meeting Date: July 18, 2023



The purpose of a staff report is to provide the Historic Preservation Commission (HPC) with a professional assessment of alteration proposals made for Local Historic District (LHD) properties. These assessments are based on the Historic District Ordinance (HDO) in compliance with M.G.L. Chapter 40C, and the associated Design Guidelines. A Staff Report is <u>not</u> a determination/decision and does not represent findings. A staff report does not constitute authorization in any form.



Page 2 of 4 Date: July 18, 2023
Case: HPC.ALT 2023.32

Site: 77 Perkins St

I. PROJECT DESCRIPTION

<u>Subject Property</u>: The locus is a residential structure at 77 Perkins Street. The main structure is a c.1830 Greek Revival structure known as the Bailey House. This property is located within East Somerville. A full description of the property is provided in the attached Form B survey held by the Massachusetts Historical Commission (MHC).

Proposal: The Applicant proposes the following:

a. Replace 10 early replacement windows with wood windows

II. FINDINGS

The HPC must make findings based on the Historic District Ordinance (HDO) in compliance with M.G.L. Chapter 40C, and associated Design Guidelines. Applicable regulations are discussed below.

A. Replace 10 replacement windows

The applicable Somerville LHD Design Guidelines is C. "Windows & Doors"

Due to the change in design elements being proposed, the HPC has purview over these features and the materials used.

Applicant Proposal

The Applicant proposes replacing 10 windows visible from the right-of-way. The 10 windows to be replaced include all windows on the front and right elevations. The subject 10 windows are early replacement windows. The Applicant is proposing to replace the existing six-over-six double-hung wood windows with six-over-six double-hung wood windows of the same design and function. The material will be solid wood. The proposal is to use true divided-light, double pane windows.

Preservation Planning Assessment:

The most relevant portions of this Design Guideline is as follows:

Whenever possible, repair and retain original or later important window elements such as sash, lintels, sill, architraves, glass, shutters and other decorative elements and hardware. When replacement of materials or elements is necessary, it should be based on physical or documentary evidence. Investigate weather-stripping and storm windows with a baked enamel finish as an alternative to the replacement of historic sash.

The Applicant is proposing to use solid wood windows and true divided light which is consistent with the above cited design guideline stating that materials should replicate original materials. The proposed windows are consistent stylistically with windows for the date of construction and architectural style of the structure.

The proposal to replace the original windows does not comply with the Design Guidelines on windows. The extant windows to be replaced are original or early replacement windows and should be preserved and restored rather than replaced. Pursuant to the Design Guidelines, alterations and additions instituted long enough ago are to be considered having historic significance in their own right.

Page 3 of 4 Date: July 18, 2023
Case: HPC.ALT 2023.32

Site: 77 Perkins St

The Applicant should pursue installing an exterior storm window and weatherstripping, re-glazing, and insulating the window instead of replacing the original window.

Should the HPC vote in favor of the window replacements, Preservation Staff recommends the following conditions be included in addition to those listed in Section IV 'Recommended Conditions' below.

- 1. The proposed windows shall be six-over-six windows and be true divided-light.
- 2. Replacement windows shall not present a warped or mirrored reflection.
- 3. Replacement windows shall not be tinted.

HPC Determination:

- The HPC must determine if, based on a review of the documentation presented, the proposed project complies with the Design Guidelines
- The HPC must structure their motion to include their own specific findings on the prosed project.

III. FINDINGS & VOTE

When bringing the matter to a vote the HPC must state their findings and reasons on why they take their position.

IV. RECOMMENDED CONDITIONS

Preservation Planning recommends the following conditions be attached to any Certificate of Appropriateness that the HPC might grant for this project:

- 1. The Applicant/Owner shall file the Certificate with the Inspectional Services Department (ISD) by uploading it to the CitizenServe permitting portal with their application for zoning compliance/building permit.
- 2. This Certificate is valid for one year. If work has not commenced within one year of the HPC's date of determination, this Certificate shall expire, and the Applicant shall re-apply for re-issuance of this Certificate. Provided that no changes have been made to the proposal, this shall be a Staff-level re-issuance of the Certificate.
- 3. All replacement windows shall be six-over-six windows and be true divided-light.
- 4. Replacement windows shall not present a warped or mirrored reflection.
- 5. Replacement windows shall not be tinted.
- 6. Any changes to this proposal made prior to the commencement of work or in-the-field changes shall be submitted to Preservation Planning for their review to determine if the changes come under the purview of the HPC.
- 7. A written narrative or descriptive checklist identifying the completion or compliance with permit conditions must be submitted to the Inspectional Services Department with a copy to preservation Planning at least fifteen (15) business days in advance of a request for a final inspection.

Date: July 18, 2023 Case: HPC.ALT 2023.32 Site: 77 Perkins St Page 4 of 4

8. The Applicant shall contact Preservation Planning at historic@somervillema.gov a minimum of fifteen (15) business days prior to final ISD walk-through so that Preservation Planning or their designee can confirm if the project was completed according to HPC approvals.



SOLD BY:

SOLD TO:

9/7/2022

Chelmsford Lumber Co 201 Boston Rd Chelmsford MA 01824-469

Chelmsford, MA 01824-4699 Fax: 978-244-0224 9/7/2022

OWNER
Shaun Lemire

Customer Quote - Pricing

QUOTE NAME PROJECT NAME QUOTE NUMBER CUSTOMER PO# TRADE ID

John Sullivan Replacement Windows 2893960 105929

& Door

ORDER NOTES: DELIVERY NOTES: Description **Unit Price** Ext. Price Line # Qty 100-1 \$991.96 \$991.96 400 Double-Hung-Insert, Equal Sash, 30 3/8 x 52 3/4, 8 1 Degrees - Moderate, AA, White Exterior Frame, White Exterior Sash/Panel, Pine w/White - Painted Interior Frame, Pine w/White - Painted Interior Sash/Panel, Jamb Liner White, Low-E4, Argon Filled, Glass / Grille Spacer Color = Stainless, Grilles: FDL, Specified Equal Light, No RO - 53 52.75 -Simulated Check Rail, 3/4", White, Pine, White, 3W2H, Hardware: Lock:Traditional, 1 Sash Locks, White (Factory Applied) Lock, Window Opening Control Device-No, Ext Stop Cover, Unit CPD Number = AND-N-132-01046-00001, -Not US Energy Star-, Version:06/23/2022 30.375 RO - 30.75

Comments: Room:None Assigned

Line #	Description	Unit Price	Qty	Ext. Price
100-2	Insect Screen 1: 400 Series Double-Hung-Insert, TWI 30.375 x 52.75 8	\$48.96	1	\$48.96
	Degrees - Moderate Full Screen Aluminum White			

Comments: Room:None Assigned

Quote #: 2893960 Print Date: 9/7/2022 3:57:45 PM UTC All Images Viewed from Exterior Page 1 of 3

Line #	Description		Unit Price	Qty	Ext. Price
200-1	400 Double-Hung-Insert, Equal Sash, 30 3/8 x 53, 8 Degrees - Moderate, AA, White Exterior Frame, White Exterior Sash/Panel, Pine w/White - Painted Interior Frame, Pine w/White - Painted Interior Sash/Panel, Jamb Liner White, Low-E4, Argon Filled, Glass / Grille Spacer Color = Stainless, Grilles: FDL, Specified Equal Light, No Simulated Check Rail, 3/4", White, Pine, White, 3W2H, Hardware: Lock:Traditional, 1 Sash Locks, White (Factory Applied) Lock, Window Opening Control Device-No, Ext Stop Cover, Unit CPD Number = AND-N-132-01046-00001, -Not US Energy Star-, Version:06/23/2022	RO - 53.25	\$991.96	8	\$7,935.68

Comments:

Room:None Assigned

— 30.375 — - RO - 30.75 —

Line #	Description	Unit Price	Qty	Ext. Price
200-2	Insect Screen 1: 400 Series Double-Hung-Insert, TWI 30.375 x 53 8 Degrees - Moderate Full Screen Aluminum White	\$48.96	8	\$391.68

Comments: Room:None Assigned

Line #	Description	Unit Price	Qty	Ext. Price
300-1	400 Double-Hung-Insert, Equal Sash, 30 3/8 x 65 1/4, 8 Degrees - Moderate, AA, White Exterior Frame, White Exterior Sash/Panel, Pine w/White - Painted Interior Frame, Pine w/White - Painted Interior Sash/Panel, Jamb Liner White, Low-E4, Argon Filled, Glass / Grille Spacer Color = Stainless, Grilles: FDL, Specified Equal Light, No Simulated Check Rail, 3/4", White, Pine, White, 3W2H, Hardware: Lock:Traditional, 1 Sash Locks, White (Factory Applied) Lock, Window Opening Control Device-No, Ext Stop Cover, Unit CPD Number = AND-N-132-01046-00001, -Not US Energy Star-, Version:06/23/2022	\$1,077.79 	5.0	\$1,077.79

Comments:

Room:None Assigned

⊢ RO - 30.75 →

Line #	Description	Unit Price	Qty	Ext. Price
	Insect Screen 1: 400 Series Double-Hung-Insert, TWI 30.375 x 65.25 8 Degrees - Moderate Full Screen Aluminum White	\$56.45	1	\$56.45

Comments: Room:None Assigned

Quote #: 2893960 Print Date: 9/7/2022 3:57:46 PM UTC All Images Viewed from Exterior Page 2 of 3

Line #	Description	Unit Price	Qty	Ext. Price
400-1	400 Patio Doors 1 Panel-FWH, 33 x 79 1/2, Left, White Exterior Frame, White Exterior Sash/Panel, Pine w/White Interior Frame, Pine w/White Interior Sash/Panel, Low-E4, Tempered, Satin Etch, Argon Filled, Glass / Grille Spacer Color = Stainless, Grilles: None, Hardware: White Hinge, Unit CPD Number = AND-N-10-01448-00004, -US Energy Star-, Version:06/23/2022	\$2,858.04	1	\$2,858.04

Comments:

Room:None Assigned

Line #	Description	Unit Price	Qty	Ext. Price
400-2	Trim Set 1: FWH Left Tribeca White PN:2577555	\$107.88	1	\$107.88

Comments: Room:None Assigned

Line #	Description	Unit Price	Qty	Ext. Price
400-3	Panel Stop 1: FWH White PN:2579687	\$14.05	1	\$14.05

Comments: Room:None Assigned

Line #	Description	Unit Price	Qty	Ext. Price
400-4	Exterior Keyed Lock 1: FWH LH Tribeca White PN:2579721	\$40.96	1	\$40.96

Comments: Room:None Assigned

TAX:	\$845.22
LABOR:	\$0.00
FREIGHT:	\$0.00
SUB-TOTAL:	\$13,523.45

CUSTOMER SIGNATURE	DATE

Thank you for choosing Andersen Windows & Doors

Quote #: 2893960 Print Date: 9/7/2022 3:57:46 PM UTC All Images Viewed from Exterior Page 3 of 3

^{*} All graphics as viewed from the exterior. ** Rough opening dimensions are minimums and may need to be increased to allow for use of building wraps or flashings or sill panning or brackets or fasteners or other items.

Front of House (South)



Entry Overhang





Window One











Window 6



Right of House (East)







Window 8





Window 10



Massachusetts Cultural Resource Information System Scanned Record Cover Page

Inventory No: SMV.310
Historic Name: Bailey House

Common Name:

Address: 77 Perkins St

City/Town: Somerville

Village/Neighborhood: East Somerville;

Local No:

Year Constructed: C 1830

Architectural Style(s): Greek Revival;

Use(s): Single Family Dwelling House;

Significance: Architecture;

Area(s): SMV.BA

Designation(s): Local Historic District (10/31/1989);

Building Materials: Wall: Wood; Wood Clapboard;

Demolished No



The Massachusetts Historical Commission (MHC) has converted this paper record to digital format as part of ongoing projects to scan records of the Inventory of Historic Assets of the Commonwealth and National Register of Historic Places nominations for Massachusetts. Efforts are ongoing and not all inventory or National Register records related to this resource may be available in digital format at this time.

The MACRIS database and scanned files are highly dynamic; new information is added daily and both database records and related scanned files may be updated as new information is incorporated into MHC files. Users should note that there may be a considerable lag time between the receipt of new or updated records by MHC and the appearance of related information in MACRIS. Users should also note that not all source materials for the MACRIS database are made available as scanned images. Users may consult the records, files and maps available in MHC's public research area at its offices at the State Archives Building, 220 Morrissey Boulevard, Boston, open M-F, 9-5.

Users of this digital material acknowledge that they have read and understood the MACRIS Information and Disclaimer (http://mhc-macris.net/macrisdisclaimer.htm)

Data available via the MACRIS web interface, and associated scanned files are for information purposes only. THE ACT OF CHECKING THIS DATABASE AND ASSOCIATED SCANNED FILES DOES NOT SUBSTITUTE FOR COMPLIANCE WITH APPLICABLE LOCAL, STATE OR FEDERAL LAWS AND REGULATIONS. IF YOU ARE REPRESENTING A DEVELOPER AND/OR A PROPOSED PROJECT THAT WILL REQUIRE A PERMIT, LICENSE OR FUNDING FROM ANY STATE OR FEDERAL AGENCY YOU MUST SUBMIT A PROJECT NOTIFICATION FORM TO MHC FOR MHC'S REVIEW AND COMMENT. You can obtain a copy of a PNF through the MHC web site (www.sec.state.ma.us/mhc) under the subject heading "MHC Forms."

Commonwealth of Massachusetts
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Massachusetts 02125
www.sec.state.ma.us/mhc

This file was accessed on: Thursday, July 13, 2023 at 11:41 AM

LHO-10/31/89 (C)

NIPE BOOKN

AREA

FORM. NO.

ASSACHUSETTS HISTORICAL COMMISSION O BOYLSTON STREET OSTON. MA 02116

East Somerville

310

	nSOMERVI
	ress77 Per
	toric Name B
	Present re
	Original re
	RIPTION
	ca. 183
	ce maps / vi
	e _ Greek Rev
catch Mars was ro tyre 7800s r	Architect

nSOMERVILLE		
re	ess <u>77</u>	Perkins Street
to	ric Name _	Bailey
1	Present	residential
	Original	residential
	ca.	
200	maps /	visual
e	Crook	D

etch Map: Draw map showing property's location ation to nearest cross streets and/or phical features. Indicate all buildings ween inventoried property and nearest stersection(s).

50000 # 19900

A REFERENCE

ALE

S QUADRANGLE

Major Alterations (with dates)

Condition good

Moved ____ Date ____

Acreage 2245 sq. ft.

Setting Near Charlestown line on north sic

of Perkins between Mt. Vernon and Mt.

Pleasant, brick apartments and mid and

late 19th century residential dwellings.

Carole Zellie - 1980

Recorded by Gretchen Schuler - 1988

Somerville Historic

Organization Preservation Commission

Date May, 1988

NATIONAL REGISTER CRITERIA STATEMENT (if applicable)

ARCHITECTURAL SIGNIFICANCE Describe important architectural features and evaluate in terms other buildings within the community.

The small three-bay, gable-end house has early 19th century dimensions with Greek Revival panelled door flanked by three-quarter side-lights, 6/6 sash, and tight eaves and returns. There is an Italianate doorhood with open brackets or braces over the side hall entrance. The side fenestration is irregular with two first and second story windows located at the end of the building. They are situated in such a fashion to indicate that this was not the end of the building in the 19th century. There is a one-story, rear ell shed.

HISTORICAL SIGNIFICANCE Explain the role owners played in local or state history and how th building relates to the development of the community.

East Somerville was one of the most densely settled parts of Somerville by the mid to late 1800s in part due to its topography and fine soil for drainage and clay for brick and pottery making. Broadway and Washington Street were main thoroughfares from the 18th century connecting Charlestown with Medford and Cambridge. Several farms cropped up in the East Somerville area and by the mid 1800s there were shops, taverns and industries with brick yards and pottery enterprises. In the mid 1800s most residents were Boston businessmen and from the 1870s many multi-family buildings were built to accommodate the increasing number of workers in the area due to the expanding brickyards, spike factories, and potteries.

Perkins Street was one of several on which 69 lots were laid out by Charles Pierce in 1845. The east end of Perkins Street borders on Charlestown and was developed by the mid 1800s. A footprint of a larger house on this lot is shown on the 19th century maps including the 1852 Draper. With closer examination of the interior cellar space, sills, foundation, and the odd fenestration pattern of the present house, it seems that this was part of a larger house situated on this lot. The footprint shows a gable end ell in this location. The Baileys who lived here were bakers.

BIBLIOGRAPHY and/or REFERENCES

- 1. Atlas of Middlesex County, Somerville: 1874 ("Mrs. Bailey"), 1884 ("Mrs. Bailey"), 1895 ("Elizabeth Bailey").
- 2. City of Somerville, Beyond the Neck: The Architecture and Development of Somerville, Massachusetts, 1983.

3. City Directories: 1870s-1890s.