

1) Repair one-story front stairs in-kind, sanding/painting where possible and replacing members with in-kind materials as needed. Final aesthetic to remain unchanged from original, with exception of removal of 1) non-historic metal screen doors added late 1900s and 2) non-historic enclosed basement access door added late 1900s, to match neighboring rowhouses.