

Parcel: 063-C-00007-000000  
MBL: 63-C-7  
Sub Type: Residential Repair

In-kind replace the front stairs and landing

Narrative:

The existing stairs and landing are deteriorated. This application proposes an in-kind replacement, matching the current design, dimensions, and materials, rather than pursuing partial repairs.

Parcel: 063-C-00007-000000  
MBL: 63-C-7  
Sub Type: Residential Repair

In-kind replace the front stairs and landing

Material Specification:

The existing porch will be replaced with a new wood porch with new posts, railings, floorboards and balusters and will match those of the existing structure in size, shape, and material.

Parcel: 063-C-00007-000000  
MBL: 63-C-7  
Sub Type: Residential Repair

Photos (3)

Front



Side, south



Side, north

