

CITY OF SOMERVILLE, MASSACHUSETTS MAYOR'S OFFICE OF STRATEGIC PLANNING & COMMUNITY DEVELOPMENT JOSEPH A. CURTATONE MAYOR

GEORGE J. PROAKIS, AICP EXECUTIVE DIRECTOR

HISTORIC PRESERVATION COMMISSION

DETERMINATION OF SIGNIFICANCE STAFF REPORT

Site: 59 Linden Avenue - Barn

Case: HPC 2019.062
Applicant Name: Fan Wang
Date of Application: August 21, 2019
Recommendation: Significant

Hearing Date: September 17, 2019

I. Historical Association

Historical Context: The house and barn at 59 Linden Avenue were constructed between 1884 and 1895. The property was owned by Wilbur P. Rice, a noted property developer who did not live at his address. See attached obituary. Residents of the building had a range of jobs from confectionary to photo engraver, furniture mover to janitor. Due to a foreclosure, the deed research came to a stop in 1936 with the bank sale to James and Margaret Fallon, originally of Irish descent. See attached research table.

Architectural Description: The barn is a side gable structure with wood doors, vinyl siding, asphalt shingle siding and an asphalt roof. The

building may have been enlarged toward the left lot line probably to accommodate a longer vehicle or used as a chicken coop. No building permits were found for this alteration. There is a pedestrian door and window on the house side of the building and a hay loft/window toward the rear property line. Interior investigation would be necessary to clearly evaluate the building for structural changes and interpretation.

The house is constructed in a simple Queen Anne style.



Page 2 of 6 Date: September 17, 219
Case: HPC 2019.062

Site: 59 Linden Avenue - Barn

Summary: The barn at 59 Linden Avenue is located behind the house and not visible from the street. Architecturally, the building has little distinction. Siding materials have been altered and the side of the building has been extended. See attached photos.

Findings on Historical Association

For a Determination of Significance, the subject building must be found either (a) importantly associated with people, events or history or (b) historically or architecturally significant (Ordinance 2003-05, Section 2.17.B). Findings for (b) are at the end of the next section.

(a) In accordance with the historic information obtained from *Findings on Historical Association*, which utilizes historic maps/atlases, City reports and directories, and building permit research, and through an examination of resources that document the history of the City, such as *Somerville Past and Present*, Staff **do not** find 59 Linden Avenue to be <u>importantly associated</u> with one or more historic persons or events, or with the broad architectural, cultural, political, economic or social history of the City or the Commonwealth.

The subject building is not found importantly associated with one or more historic persons or events. While the land was probably developed by Wilbur P. Rice, he is known to have built many hundred homes in Somerville. It is associated with the broad architectural, cultural, economic and social history of the City due its construction type and use. Barns and stable were necessary adjuncts to the pre-automotive era.

II. Historical and Architectural Significance

The findings for historical and/or architectural significance of a historic property address the period, style, method of building construction and association with a reputed architect or builder of the subject property, either by itself of in the context of a group of buildings of structures (Ordinance 2003-05, Section 2.17.B).

The period of significance for the 59 Linden Avenue house and barn begins with its construction circa 1895.

Integrity

The National Park Service identifies historic integrity as the ability of a property to convey significance. A property should possess sufficient integrity to convey, represent or contain the values and qualities for which it is judged significant; therefore, the following is an identification and evaluation of these qualities and alterations as they affect the ability of the subject property to convey significance.

- a. <u>Location:</u> The building has not been moved. It is located one house in from Summer Street on Linden Avenue, a quiet neighborhood street. The barn is located at the back of the lot behind the house against the hill.
- b. <u>Design:</u> The building barn is a simple gabled rectangle with low side addition.
- c. <u>Materials</u>: The building is constructed with wood. Siding materials are varied. They include plywood, board, brick patterned asphalt, and vinyl.
- d. <u>Alterations:</u> The siding, doors and windows have been altered. The low side extension of the building may or may not be an alteration.

Evaluation of Integrity: Despite the alterations to the building, the barn retains integrity of form and massing.

Findings for Historical and Architectural Significance

Page 3 of 6 Date: September 17, 219
Case: HPC 2019.062

Site: 59 Linden Avenue - Barn

For a Determination of Significance, the subject building must be found either (a) importantly associated with people, events or history or (b) historically or architecturally significant (Ordinance 2003-05, Section 2.17.B). Findings for (a) can be found at the end of the previous section.

(b) In accordance with the *Finding on Historical and Architectural Significance*, which addresses period, style, method of building construction, and association with a reputed architect or builder, either by itself or in the context of a group of buildings or structures, as well as integrity, which assess the ability of the property to convey significance, Staff find 59 Linden Avenue barn historically or architecturally significant.

The subject barn at 59 Linden Avenue is found historically and architecturally significant due to its method of building construction and its association with pre-automotive Somerville.

III. Recommendation

Recommendations are based upon an analysis by Historic Preservation Staff of the permit application and the required findings for the Demolition Review Ordinance, which requires archival and historical research, and an assessment of historical and architectural significance, conducted prior to the public meeting for a Determination of Significance. This report may be revised or updated with a new recommendation and/or findings based upon additional information provided to Staff or through further research.

For a Determination of Significance, the structure must be either (A) listed on the National Register or (B) at least 50 years old.

(A) The structure is NOT listed on or within an area listed on the National Register of Historic Places, nor is the structure the subject of a pending application for listing on the National Register.

OR

(B) The structure, circa 1895, is at least 50 years old.

AND

For a Determination of Significance under (B), the subject building must be found either (a) importantly associated with people, events or history or (b) historically or architecturally significant.

(a) In accordance with the *Findings on Historical Association*, which utilizes historic maps/atlases, City reports and directories, and building permit research, and through an examination of resources that document the history of the City, **Staff recommend that the Historic Preservation Commission do NOT find 59 Linden Avenue - barn importantly associated with one or more historic persons or events, but do find the barn associated with the broad architectural, cultural, political, economic or social history of the City or the Commonwealth.**

The barn at 59 Linden Avenue is not found importantly associated with one or more historic persons or events. While the land was probably developed by Wilbur P. Rice, he is known to have built many hundred homes in Somerville. It is associated with the broad architectural, cultural, economic and social history of the City due its construction type and use. Barns and stable were necessary adjuncts to the pre-automotive era.

Date: September 17, 219 Case: HPC 2019.062 Site: 59 Linden Avenue - Barn

OR

(b) In accordance with the *Findings on Historical and Architectural Significance*, which addresses period, style, method of building construction, and association with a reputed architect or builder, either by itself or in the context of a group of buildings or structures, as well as integrity, the ability to convey significance, **Staff recommend that the Historic Preservation Commission find 59 Linden Avenue barn historically and architecturally significant.**


The subject barn at 59 Linden Avenue is found historically and architecturally significant due to its method of building construction and its association with pre-automotive Somerville.



Date: September 17, 219 Case: HPC 2019.062 Site: 59 Linden Avenue - Barn




1874 Hopkins Atlas Plate 13



1895 Bromley Plate 16

Date: September 17, 219 Case: HPC 2019.062 Site: 59 Linden Avenue - Barn



Jause Number	~ /	ι I	\	OCCUPALIS AGE	\	$I_{\overline{z}}$	₹ /°	,	\	
	LOCATION		NAME	AGE CUPA	\	PLACE OF BIRTH	Immigration Year	SOURCE TE	NOTES	
[m] \	L10N	\~\	£ /	# /2	<u> </u>	RTH ROT	ratio \	Ē	/ ES	
<i>a</i> /		\ \	\	\		1	-	\		
	59 Linden Avenue 59 Linden Avenue		Dwight E. Carr Dwight E. Carr		Confectioner Confectioner, Boston			1890 City Directory 1892 City Directory		
	59 Linden Avenue	0	Wilbur P. Rice		Confectioner, Boston			1895 Bromley Atlas Plan	e 16	
	59 Linden Avenue		Herbert L. Jones		Confectionary			1895 City Directory		
	59 Linden Avenue		George E. Richards		Bookkeeper			1895 City Directory		
	59 Linden Avenue		Herbert L. Jones		Confectionary			1897 City Directory		
	59 Linden Avenue 59 Linden Avenue		George H. Richards Herbert L. Jones		Bookkeeper Confectionary			1897 City Directory 1898 City Directory		
	59 Linden Avenue		Charles Howard		Brakeman			1899 City Directory		
	59 Linden Avenue	0	W. P. Rice		Drakeman			1900 Stadly Atlas Plate	16	
	59 Linden Avenue		Michael J. Leahy		Milkman			1901 City Directory		
	59 Linden Avenue		Michael J. Leahy		Milkman			1902 City Directory		
	59 Linden Avenue 59 Linden Avenue		Michael Leahy William G. Bernard		Photo Engraver, Boston			1903 City Directory 1905 City Directory		
	59 Linden Avenue		William G. Bernard		Photo Engraver, Boston			1905 City Directory		
	59 Linden Avenue		Rhoda A. M. Barnard		Widow of Albert F. Barnard			1906 City Directory		
	59 Linden Avenue		Rhoda A. M. Barnard		Widow of Albert F. Barnard			1907 City Directory		
	59 Linden Avenue		William G. Bernard		Photo Engraver, Boston			1909 City Directory		
	59 Linden Avenue	_	Rhoda A. M. Barnard		Widow of Albert F. Barnard			1909 City Directory		
	59 Linden Avenue 59 Linden Avenue	_	William G. Bernard Rhoda A. M. Barnard		Photo Engraver, Boston Widow of Albert F. Barnard			1910 City Directory 1910 City Directory		
0/760	59 Linden Avenue		Rhoda M. Barnard (mother)	80	dow of Albert F. Daniald	Vermont		1910 US Census		
0/760	59 Linden Avenue		Kate Barnard (wife)	56		Massachusetts		1910 US Census		
0/760	59 Linden Avenue		Alice M. Barnard (sister)	50		Massachusetts		1910 US Census		
0/760	59 Linden Avenue	0	William G. Barnard (head)	47	Photo Engraver	Massachusetts		1910 US Census		
	59 Linden Avenue	_	William G. Bernard		Photo Engraver, Boston Photo Engraver, Boston			1911 City Directory		
	59 Linden Avenue 59 Linden Avenue		William G. Bernard Rhoda A. M. Barnard		Widow of Albert F. Barnard			1912 City Directory 1912 City Directory		
	59 Linden Avenue		Rhoda A. M. Barnard		Widow of Albert F. Barnard			1913 City Directory		
	59 Linden Avenue		William G. Bernard		Photo Engraver, Boston			1914 City Directory		
	59 Linden Avenue		Rhoda A. M. Barnard		Widow of Albert F. Barnard			1914 City Directory		
	59 Linden Avenue		John H. Ford		Painter			1916 City Directory		
	59 Linden Avenue 59 Linden Avenue		Edward J. Ford Mrs. Elizabeth Ford		Driver			1916 City Directory		
	59 Linden Avenue		John H. Ford		Painter			1918 City Directory 1918 City Directory		
	59 Linden Avenue		John H. Ford		Painter			1919 City Directory		
	59 Linden Avenue		Lucy Ford		Bookbinder			1920 City Directory		
	59 Linden Avenue		John H. Ford		Painter			1920 City Directory		
	59 Linden Avenue		Elizabeth Ford					1920 City Directory		
7/53	59 Linden Avenue 59 Linden Avenue	0	Edward Ford Elizabeth A. Ford (head)	75	Furniture Mover	Ireland		1920 City Directory 1920 US Census		
1/53	59 Linden Avenue		Lucy J. Ford (sister)	72		Ireland		1920 US Census		
/53	59 Linden Avenue		John H. Ford (brother)	59		Ireland		1920 US Census		
7/53	59 Linden Avenue		Edward J. Ford (brother)	57		Ireland		1920 US Census		
7/53	59 Linden Avenue		John Miller (grand-nephew)	13		Massachusetts		1920 US Census		
27/53	59 Linden Avenue		Harold F. Miller (grand-nephev	11		Massachusetts		1920 US Census		
	59 Linden Avenue 59 Linden Avenue		Lucy Ford John Ford		Painter			1924 City Directory 1924 City Directory		
	59 Linden Avenue		Edward Ford		Janitor			1924 City Directory		
	59 Linden Avenue		John Ford		Painter			1925 City Directory		
	59 Linden Avenue		Edward Ford		Janitor			1925 City Directory		
	59 Linden Avenue		John Ford		Painter			1927 City Directory		
	59 Linden Avenue	О	Bernasconi Mary Bernasconi		Wife of Edward Bernasconi			1927-2-660 Building Per 1929 City Directory	mit Enlarge pantry in	rear
	59 Linden Avenue		Marie Bernasconi		Wife of Aduiado Bernasconi			1929 City Directory		
	59 Linden Avenue		Joseph E Caselli		Buss Boy			1929 City Directory		
	59 Linden Avenue		Aduiado Bernasconi		Mason			1929 City Directory		
5/419	59 Linden Avenue	0	Edward R. Bernasconi (head)		Mason	Italy	1909	1930 US Census		
5/419 5/419	59 Linden Avenue 59 Linden Avenue		Mary Bernasconi (wife) Joseph M. Castelle (stepson)	44 19	Busboy, Hotel	Italy Massachusetts	1906	1930 US Census 1930 US Census		
5/419	59 Linden Avenue 59 Linden Avenue	_	Michael A. Castelle (stepson)	13	Dusboy, 110tel	Massachusetts Massachusetts		1930 US Census 1930 US Census		
	59 Linden Avenue		Mary Bernasconi	-13	Wife of Edward Bernasconi			1933 City Directory		
	59 Linden Avenue		Joseph E Caselli		Buss Boy			1933 City Directory		
	59 Linden Avenue		Edward Bernasconi		Mason			1933 City Directory		
212	59 Linden Avenue	0	James Fallon & Margaret Fa		Classic Mal C 7	Litab E C		1936 Deed f6047/350	from Cambridge S	avings Bank
	59 Linden Avenue 59 Linden Avenue	0	James Follon (head) Margaret M. Follon (wife)	45 43	Glycerine Maker, Soap Fac	Irish Free State Irish Free State		1940 US Census 1940 US Census		
	59 Linden Avenue	+	James Follon Junior (son)	10		Massachusetts		1940 US Census		
	59 Linden Avenue		John F. Follon (son)	9		Massachusetts		1940 US Census		
	59 Linden Avenue		Francis Follon (son)	5		Massachusetts		1940 US Census		
	59 Linden Avenue	О	Michael J. Colbert & Mary J	. Colber	t			1974 Deed 12666/45	from estate of Mar	garet M. Fall
	59 Linden Avenue	o	Fan Wang & Marc Wagner					2019 Deed 73137/47	from estate of Mic	hael J. Colber
		+								
							-			

CANDIDATES OUESTIONED.

Harvard Political Club Wants to Know Their Attitude as Regards the income Tax.

The Harvard political club yesterday ent by registered mail a circular let-er to every candidate for the Massater to

ter to every candidate for the Massa-chusetts house and senate, asking them their stand on the income tax. Officers of the club, which is a ron-partisan political association, are John Ray Gilman pres, and Roger Sherman Hoar treas The former is prominent in republican and the latter in demo-cratic state politics On the executive committee are Mr Harding, a leading member of the Harvard socialist club, and Mr Loring, a republican alderman of Beverly.

BUILT 1500 BUILDINGS.

Funeral of Wilbur P. Rice to Be Held Wednesday Morning From St Cecilia's Church, Back Bay.

The funeral of Wilbur P. Rice, a Somerville business man, who died a couple of days ago at his home, 200 Bay State rd, after a long illness, will be held tomorrow morning. Requiem ser-vices will take place in St Cecilia's

church, Back Bay, at 10 o'clock.

He was born in Bear River, N S, 55
years ago. For the past 30 years he
has been in the real estate and lumber
business in Somerville, and during that time it is said he built as many as 1500 houses and business blocks in that city He leaves a wife, who was Miss Mary Donnelly of this city, and four daughters and a son, Walter A. Rice, who has been engaged with his father who has be n business

ELECTRICIAN BADLY HURT.

Whidden Struck by Wagon Wheel at Meirose While Attempting to Stop Frightened Horse.

MELROSE, Oct 18—Robert H. Whidden, aged 41. electrician of the Melrose fire department and son-in-law of Chief Engineer Joseph Edwards, was seriously injured this evening on Irving st.

In company with Joe Marris, for-

In company with Joe Marris, formerly plicher of the Boston Americans, Whidden had been trimming trees on the street to clear the wires of the electric signal service, and while Harris was cutting a limb Whidden stood at the foot of the tree in charge of the horse and wagon of the department. The limb falling from the tree struck the horse and caused him to run away. In trying to stop him Whidden was truck in the back of the head by a front wheel of the wagon and was knocked down. He was rendered unconscious and was taken to the Melrosa hospital, where he was found to be badly cut about the face.

The hospital authorities fear that his skull is also fractured and consider his condition dangerous.

TO AID REV FR DI MILLA.

Catholics Have Party Attended by About 700. Italian

The Italian Catholics of the South End held a reunion last evening in Odd Fel-lows' hall, Tremont st. in aid of the church of Our Lady of Pompeli on Har-rison av. near Dover st. The affair was a big success.

was a big success.

A gathering of about 700, about one-half of whom were Italians, attended. The guests were entertained by Rev Fr Pasquale Di Milla during the evening. Francis P Aieta was floor director, assisted by Edward A. Campana and John B. Romeo, who was chief of aids. The executive committee included Rev Fr Di Milla, Miss Mildred L. Russo, Miss Katherine L. Delaney, Miss Katherine Costello, Miss Helena Tortorella and Miss Elizabeth Werner.