

# CITY OF SOMERVILLE, MASSACHUSETTS MAYOR'S OFFICE OF STRATEGIC PLANNING & COMMUNITY DEVELOPMENT KATJANA BALLANTYNE MAYOR

GEORGE J. PROAKIS EXECUTIVE DIRECTOR

PLANNING DIVISION HISTORIC PRESERVATION

## STEP 2: DETERMINATION OF PREFERABLY PRESERVED STAFF REPORT

**Site:** 53 Broadway

**Case:** HPC.DMO 2022.02

**Applicant:** Ben Rogan

Owner: CDA Realty, LLC

**Legal Ad:** The Applicant seeks to demolish

a principal structure constructed a minimum of 75 years ago.

**HPC Meeting Date:** March 15, 2022



The purpose of a staff report is to provide the Historic Preservation Commission (HPC) with additional information and professional assessments regarding properties that are proposed for demolition. These assessments are based on the criteria allowed for consideration by the HPC in accordance with the Demolition Review Ordinance (DRO). A Staff Report is <u>not</u> a determination/decision, nor does it constitute authorization in any form.

#### I. SUMMARY OF February 15, 2022 MEETING

At their regular public meeting on February 15, 2022, the HPC declared the structure at 53 Broadway to be "Historically Significant". Due to this determination, 53 Broadway moved on to the second step in the demolition review process, which calls for the HPC to determine whether or not the building should be "Preferably Preserved". A determination of "preferably preserved" does not permanently halt demolition of a building.



Date: March 15th, 2022 Case: HPC.DMO 2022.02 Site: 53 Broadway

## II. BUILDINGS UNDER CONSIDERATION

The building at 53 Broadway is a 3 story, mansard style residential structure. 53 Broadway was constructed at some time around 1887.

Right: 53 Broadway



Right: Rear



Right: Right Elevation



Date: March 15th, 2022 Case: HPC.DMO 2022.02 Site: 53 Broadway



Above: Context Map for 53 Broadway.

## III. ADDITIONAL INFORMATION

Preservation Planning has not uncovered any additional information in the intervening weeks since the Historic Significance vote.

To see the historic maps and research regarding structure at 53 Broadway and a general history of the area, see the February 15, 2022, staff report on Historic Significance.

## IV. <u>DETERMINATION</u>

The HPC must determine one of the following for the structure at 53 Broadway:

- a. That the building is Preferably Preserved.
- b. That the building is not Preferably Preserved.
- c. That the building is not Preferably Preserved with Conditions.

See the following section V "Findings" for guidance

(Continued on next page)

Page 5 of 5

Date: March 15th, 2022
Case: HPC.DMO 2022.02

Site: 53 Broadway

## V. <u>FINDINGS</u>

The HPC need to make determinations of whether the structure is to be preferably preserved and adopt findings.



53 Broadway

#### a. Preferably Preserved

For a determination of *preferably preserved*, the HPC must make the following finding:

- That the demolition of the structure at **53 Broadway** would be detrimental to the architectural, cultural, political, economic, or social heritage of the City.

If the HPC makes the above finding, the Commission must state their reasons why they take either position.

#### b. Not Preferably Preserved

If the HPC makes the above finding, the Commission must state their reasons why they take either position.

#### c. Not Preferably Preserved with Conditions

For a determination of <u>NOT preferably preserved with Conditions</u>, the HPC must make the following finding:

- That the structure at **53 Broadway** do not meet any of the criteria to be "preferably preserved.". The HPC may add any or all of the following as conditions to this determination:
  - 1. photographic documentation of the building to be demolished;
  - 2. architectural renderings of the building to be demolished;
  - 3. identification of materials for salvage of material; and/or,
  - 4. a plan for installation of historic or interpretive signage at or near the site.

If the HPC makes the above finding, the HPC must state their reasons why they take this position.

### VI. VOTE

When bringing the matter to a vote, the HPC must include the reasons why the structure at 53 **Broadway** is or is not "preferably preserved".