



Center Drawer Installation


Turnstone 5770



Tools

Power Driver
w/Phillips or
Square Tip





Using pre-drilled holes in underside of desk top, install (4) screws and spacers as shown above.